



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22009790/Rvy3e2 Date: 22/11/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4141P	Veh. Inspected	FBK 7270J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/09/22/2084	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	04/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400SF MANUAL	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	NC421604369	Colour	MULTI COLOUR	
Odometer	56083 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60Z R17	BRIDGESTONE	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60Z R17	BRIDGESTONE	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/09/2022	Inspection Date	06/10/2022	
Survey held at	SIN BOON MOTOR CO 10, ADMIRALTY STREET #01-10/11 NORTHLINK BUILDING . SINGAPORE 757695			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	