

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

TP A1G.
Veron.
WDDKJ3EB2EF225564

SLS

S1S6728C Mercedes Benz E200

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bootlid assy <i>Dented</i>	\$ 1,753.00 ✓
2	1	Rear bootlid logo <i>new</i>	\$ 88.00 ✓
3	1	Rear bootlid weatherstrip <i>cut</i>	\$ 216.00 ✓
4	1	Rear bootlid inner trim board <i>new</i>	\$ 226.00 ✓
5	1	Rear bootlid lock inner cover <i>2nd</i>	\$ 165.00 ✓
6	1	Rear bootlid lock mechanism <i>2nd</i>	\$ 267.00 ✓
7	2	Rear bootlid rubber stopper <i>new</i>	\$ 68.00 +
8	1	Rear bootlid breakdown warning sign <i>new</i>	\$ 180.00 +
9	2	Rear bootlid hinges <i>new</i>	\$ 195.00 ✓
10	2	Rear bootlid hinges cover <i>new</i>	\$ 187.00 ✓
11	1	Rear bootlid 'E200' emblem	\$ 81.00 ✓
12	1	Rear bootlid 'cycle carriage' emblem	\$ 86.00 ✓
13	1	Rear bootlid '7G' emblem	\$ 76.00 ✓
14	1	Rear bootlid 'Tronic' emblem	\$ 82.00 ✓
15	1	Rear bootlid chrome moulding <i>cracked</i>	\$ 199.00 ✓
16	1	Rear left taillamp <i>LH cracked</i>	\$ 828.00 ✓
17	1	Rear right taillamp <i>new</i>	\$ 828.00 +
18	1	Rear bootlid left taillamp <i>cracked</i>	\$ 623.00 425.
19	1	Rear bootlid right taillamp <i>new</i>	\$ 623.00 +
20	1	Rear end panel <i>Dented</i>	\$ 1,265.00 1180.
21	1	Rear end panel top garnish <i>cracked</i>	\$ 182.00 ✓
22	1	Rear bumper assy <i>cracked</i>	\$ 1,690.00 ✓
23	1	Rear bumper center chrome moulding <i>cut</i>	\$ 380.00 ✓
24	1	Rear bumper left chrome moulding <i>3pc</i>	\$ 196.00 ✓
25	1	Rear bumper right chrome moulding <i>3pc</i>	\$ 196.00 ✓
26	1	Rear bumper lower trim <i>cracked</i>	\$ 455.00 ✓
27	1	Rear bumper tow cover <i>new</i>	\$ 98.00 +
28	1	Rear bumper inner lock switch sensor <i>new</i>	\$ 375.00 +
29	1	Rear bumper inner brake assist sensor <i>new</i>	\$ 380.00 +
30	1	Rear bumper reinforcement <i>Dented</i>	\$ 990.00 780.
31	1	Rear bumper left side retainer <i>3pc</i>	\$ 81.00 +
32	1	Rear bumper right side retainer <i>3pc</i>	\$ 81.00 +
33	1	Rear bumper left top basic carrier <i>3pc</i>	\$ 67.00 ✓
34	1	Rear bumper right top basic carrier <i>3pc</i>	\$ 67.00 ✓
35	1	Rear bumper left bottom basic carrier <i>3pc</i>	\$ 88.00 +
36	1	Rear bumper right bottom basic carrier <i>3pc</i>	\$ 88.00 +
37	1	Rear bumper left side stability <i>3pc</i>	\$ 165.00 +
38	1	Rear bumper right side stability <i>3pc</i>	\$ 165.00 +
39	1	Rear bumper center bracket <i>cracked</i>	\$ 155.00 ✓
40	1	Rear bumper left lower bracket <i>3pc</i>	\$ 62.00 +
41	1	Rear bumper right lower bracket <i>3pc</i>	\$ 62.00 +
			\$ 14,059.00
Less 10%			\$ 1,405.90
			\$ 12,653.10

9814

8652-60

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJS6728C Mercedes Benz E200

No	Qty	Parts Description	Estimated Parts Price
42	4	Rear mercedes benz parking sensor <i>2 pieces dyed</i>	\$ 1,528.00 <i>560</i>
43	1	Rear exhaust silencer assy <i>new</i>	\$ 1,487.00 <i>+</i>
44	2	Rear exhaust mountings <i>new</i>	\$ 88.00 <i>+</i>
45	1	Rear spare tyre top board <i>Del d</i>	\$ 295.00 <i>✓</i>
46	2	Rear no plate lamp <i>new</i>	\$ 128.00 <i>+</i>
47	1	Rear tool sponge carrier <i>new</i>	\$ 295.00 <i>+</i>
48	1	Rear bootlid key lock <i>new</i>	\$ 126.00 <i>+</i>
49	1	Rear left exhaust heat shield <i>2</i>	\$ 167.00 <i>+</i>
50	1	Rear right exhaust heat shield <i>new</i>	\$ 167.00 <i>+</i>
51	1	Rear centre exhaust heat shield	\$ 178.00 <i>+</i>
			\$ 4,459.00
Less 10%			\$ 445.90
			\$ 4,013.10

855
769.50

Special Nett Items

1	1 set	Rear bumper clips <i>new</i>	\$ 60.00 <i>30</i>
2	1 set	Rear end panel top garnish clips <i>new</i>	\$ 50.00 <i>20</i>
3	1 set	Rear bootlid inner trim board clips <i>new</i>	\$ 50.00 <i>+</i>
4	1	Rear view camera <i>Del d</i>	\$ 450.00 <i>380</i>
5	1	Rear bootlid third brake lamp <i>cut</i>	\$ 450.00 <i>280</i>
6	1	Rear bootlid top spoiler sealant <i>new</i>	\$ 80.00 <i>+</i>
7	1	Rear bootlid top spoiler <i>new</i>	\$ 750.00 <i>+</i>
8	1	Rear license plate <i>new</i>	\$ 100.00 <i>+</i>
9	1	Rear end panel sealant <i>new</i>	\$ 120.00 <i>60</i>
			\$ 2,110.00

770

Total parts

\$ 18,776.20

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJS6728C Mercedes Benz E200

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,600.00 <i>900</i>
2	To putty and spray painting rear portion.	\$ 1,600.00 <i>900</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>30</i>
4	To remove and install rear bootlid lock mechanism . <i>8 things -</i>	\$ 80.00 <i>✓</i>
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 <i>60</i>
6	To apply anti rust proofing to rear affected area.	\$ 120.00 <i>60</i>
7	To remove and install rear exhaust silencer assy	\$ 120.00 <i>+</i>
8	To remove and install rear parking sensor.	\$ 80.00 <i>80</i>
9	To remove and install rear view camera.	\$ 80.00 <i>50</i>
10	Towing service.	\$ 100.00 <i>✓</i>
Total labour :		\$ 3,970.00

Total parts : \$ 18,776.20
Total labour : \$ 3,970.00
Total repair cost : \$ 22,746.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
L/S 04/10/22
06 Days

Total: 12422.10

L/S : 9.9K

9.9K