

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0785/2022/EQ
DATE : 9-Sep-22
WIP : 41130

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/9/2022.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. TERENCE TEE
ADDRESS : 21 SAMPAN PLACE
#08-06
SINGAPORE 436593
TELEPHONE : HP +65 91800498
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070153145
VEHICLE NO : **SMW 7007 K**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI S-TRONIC
MODEL YEAR : 30/10/2020
ENGINE NO : DEM 024459
CHASSIS NO : WAUZZZF51LA019821
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Sep-22
PLACE OF ACCIDENT : SLE TOWARDS TPE 100M AFTER EXIT 5

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 7007 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 450.00 ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS SILL PANEL TRIM AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,800.00 1000	
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS SILL PANEL TRIM.	\$ 4,500.00 1100.	
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 9,702.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 7007 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	de ✓
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	X
3	FRONT BUMPER AIR GUIDE - LH	1	\$ 72.00	?
4	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	X
5	FRONT BUMPER TRIM - LH	1	\$ 54.00	X
6	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	?
7	FRONT FENDER - LH	1	\$ 1,189.00	bt ✓
8	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	X
9	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 83.00	X
10	FRONT FENDER BRACKET - LH	1	\$ 41.00	X
11	FRONT FENDER RIVET	6	\$ 23.00	new ✓
12	FRONT FENDER BRACE - LH	1	\$ 132.00	?
13	FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	1	\$ 55.00	?
14	FRONT FENDER BRACKET - LH	1	\$ 40.00	?
15	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00	X
16	FRONT WHEEL HOUSING LINER - LH	1	\$ 299.00	X
17	FRONT WHEEL SPOILER - LH	1	\$ 82.00	X
18	FRONT WHEEL SPOILER TRIM - LH	1	\$ 39.00	X
19	FRONT FENDER STONE CHIP GUARD - LH	1	\$ 57.00	X
20	FRONT FENDER LOWER BRACKET - LH	1	\$ 27.00	?
SUB TOTAL SPARE PARTS		:	\$ 5,049.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 7007 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER CHROME TRIM - LH	1	\$ 171.00	ne ✓
22	FRONT SIDE MEMBER TRIM - LH	1	\$ 916.00	X
23	FRONT SIDE MEMBER TRIM ATTACHMENT PARTS	1	\$ 136.00	X
24	FRONT SIDE MEMBER TRIM ADHESIVE TAPES	1	\$ 221.00	X
25	FRONT ALUMINIUM RIM - LH	1	\$ 1,889.00	cut ✓
26	FRONT ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	ne ✓
27	HEADLIGHT - LH	1	\$ 8,172.00	X
28	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 16,958.00	
TOTAL LABOUR CHARGES		:	\$ 9,702.00	
GRAND TOTAL		:	\$ 26,660.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 9749 5749
4/10/77 P111a
Not Authorise Ex: tba
Resurvey before paint 04 days - 05 days.
taufik@khairauto.com.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT