3/16/23, 2:53 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22009799/TPA3Q2

16/03/2023 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2001207703 **Claimant Vehicle** 

SHC7211B Insured Vehicle No: SMJ7843G No:

Date of Loss: 29/09/2022 Nature of Claim: TP Claim No: 202222007155JK

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SHC7211B** 

HYUNDAI 140. 1.7 D CRDI F/L ABS AIRBAG Make & Model:

Engine No: D4FDGU668484 4DR (A)

Reg. Date: KMHLB41UMGU086984 07/04/2016 (Man. Year: 2015) Chassis No: Odometer: 745950 km

Colour: Yellow 1685 cc

**Engine Capacity:** Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): **Engine Modification:** Yes No

**CONDITION OF TYRES** 

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Rear Left Side: West Lake 6 mm West Lake 6 mm Rear Right Side: Front Right Side: West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,547.37	2,185.77	2,361.60	51.93
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,700.00	1,365.00	335.00	19.71
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,247.37	3,550.77	2,696.60	43.16
	Approved Total (Overridden) (S\$)		1,650.00		
	(S\$)	6,247.37	1,650.00	4,597.37	73.59
	+ GST 7.00/7.00% (S\$)	437.32	115.50	321.82	73.59
	Nett Amount (S\$)	6,684.69	1,765.50	4,919.19	73.59
	+ Loss of Use (3.5 x S\$	550.00/day) (S\$)	175.00		
	+ Car Rental (3.5 x S\$110.67/day) (S\$)		387.35		
	+ Doc/\$	Search Fee (S\$)	2.00		
	Ne	ett Liability (S\$)	2,329.85		

**INSPECTION** 

Date of Assignment: 04/10/2022

ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Date Inspected: 04/10/2022 Inspected At:

Singapore 508969

Estimated Period of Repair: 3.0 days

MOHD TAUFIKH BIN HAMID Adjuster: Manager: **CHEW HSIAO TONG**  NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

### **REPAIR DETAILS**

#### Reference

3/16/23, 2:53 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2023)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC7211B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR PANEL LH	Bent	2,707.70 FL	*2,707.70 FL
2	1		*REAR DOOR PANEL LH	Repair	2,416.80 FL	*- FL
3	1		*ROCKER GARNISH LH	Repair	732.00 FL	*- FL
4	1		*FRONT DOOR COMFORT LOGO STICKER	Necessary	75.00 FS	*75.00 FS
5	1		*REAR DOOR APP LOGO	Necessary	80.00 FS	*80.00 FS
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	6,011.50	2,862.70
			- List Item Discount on L Items	s 25.00/25.00% (S\$)	1,464.13	676.93
				Total Parts (S\$)	4,547.37	2,185.77
			Report was unsubmitted during thi	s print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	600.00	525.00
2	SPRAY PAINTING CHARGE	New	800.00	750.00
3	REMOVE/REPLACE FRONT & REAR DOOR PARTS	New	180.00	60.00
4	TUFF KOTE	New	120.00	30.00
		Gross Labour Cost (S\$)	1,700.00	1,365.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >