

CITY CAR PARTS LTD E

REPAIR ESTIMATE*

VEHICLE NO SHC7211B
 MAKE REG 07.04.2016
 MODEL I-40

DATE 28.09.2022
 CHIANG/ALLIANZ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR PANEL LH			\$2,707.70
1	REAR DOOR PANEL LH			\$2,416.80
1	ROCKER GRANISH LH			\$732.00
	SUB TOTAL		2707.70	\$5,856.50
	25.00%			\$1,464.12
	DISCOUNTED TOTAL		2030.77	\$4,392.37
1	FRONT DOOR COMFORT LOGO STICKER			\$75.00
1	REAR DOOR APP LOGO			\$80.00
				\$155.00
	Labour Charge			\$25
	Panel Beating			\$600.00
	Spray Painting Charge			\$800.00
	Remove/replace front & rear door parts.			\$180.00
	Tuff Kote			\$120.00
	TOTAL LABOUR		1365	\$1,700.00
	ESTIMATE TOTAL		3550.77	\$6,247.37
			45 \$1150	
			23 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpin 27495749
 WP 4/10/22 @ 3pm
 Tanpin @ 1st auto on
 2 days
 45 Resurvey after repair

- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: