

Date: 03/10/2022

Vehicle No: SJH8966A

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FJXMC263263-2021

Reg.Year: 2021

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GBD455B

Date of Accident: 29/09/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		<i>R</i> \$953.27
2	REAR DOOR WEATHERSTRIP RH	1		<i>SL</i> \$88.79
3	REAR FENDER RH	1		<i>B</i> \$1,345.79
4	REAR FENDER QUARTER GLASS RH	1		<i>mg</i> <i>mc</i> \$280.37
SUB TOTAL				\$2,668.22
LESS 10%				-\$266.82
PARTS TOTAL				\$2,401.40

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR INNER TRIM BOARD CLIPS	1		<i>nn</i> \$50.00
2	REAR FENDER QUARTER GLASS SEALANT RH	1		<i>mc</i> \$80.00
S/N TOTAL				\$130.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH & ETC.

\$600.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

nn \$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$300.00

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS RH, REAR FENDER QUARTER GLASS SEALANT RH & ETC.

\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00

LABOUR TOTAL \$1,920.00

TING AN

TOTAL \$4,451.40

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 6 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

