

Date: 03/10/2022
Vehicle No: SJH8966A
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FJXMC263263-2021
Reg. Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBD455B
Date of Accident: 29/09/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		\$953.27
2	REAR DOOR WEATHERSTRIP RH	1		\$88.79
3	REAR FENDER RH	1		\$1,345.79
4	REAR FENDER QUARTER GLASS RH	1		\$280.37
SUB TOTAL				\$2,668.22
LESS 10%				-\$266.82
PARTS TOTAL				\$2,401.40

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR INNER TRIM BOARD CLIPS	1		\$50.00
2	REAR FENDER QUARTER GLASS SEALANT RH	1		\$80.00
S/N TOTAL				\$130.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. \$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH & ETC. \$600.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH. \$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH. \$300.00

LABOUR CHARGES TO REMOVE & REPLACE REAR FENDER QUARTER GLASS RH, REAR FENDER QUARTER GLASS SEALANT RH & ETC. \$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM. \$120.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,920.00

TOTAL \$4,451.40

TING AN

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554590
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

10, Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011

