



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 193R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	TAIL LAMP @\$360.00	O/S CRACKED	720.00	360.00
2	TAIL LAMP BRACKET @\$186.50	O/S BENT	373.00	186.50
	LESS 25% DISCOUNT		-273.25	-136.62
			819.75	409.88
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	REAR NUMBER PLATE BRACKET (SN)	BENT	198.50	198.50
1	REAR REINFORCEMENT (SN)	NOT NECESSARY	2,800.00	-
1	REAR NUMBER PLATE LAMP (SN)	NOT NECESSARY	120.00	-
1	REAR STEP BRACKET (WOODEN) (SN)	CRACKED	1,500.00	400.00
1	REAR CARGO BED REAR FRAME (SN)	TO REPAIR SEE LABOUR	3,800.00	-
9	REAR CARGO BED BOTTOM BEAMS (WOODEN) @ \$1,500.00 (SN)	CRACKED (3 PIECES)	13,500.00	1,500.00
2	CARGO BED CHASSIS MEMBER (WOODEN) @\$6,500.00 (SN)	O/S CRACKED	13,000.00	2,000.00
6	CARGO BED U CLIP @\$250.00 (SN)	NOT NECESSARY	1,500.00	-
1	TAILGATE (SN)	CRACKED	3,800.00	1,800.00
			40,268.50	5,948.50
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAXE, ALIGN. INCLUSIVE OF THE REPAIR OF REAR CARGO BED REAR FRAME.		1,400.00	650.00
	TO PUTTY, SPRAY PAINT, POLISH, WAX.		1,000.00	300.00
	BULB CHECKING, WIRING.		180.00	30.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	200.00	-
	REMOVE AND REFIX CARGO BED.		2,800.00	650.00
	REMOVE AND REFIX CANOPY.	NOT NECESSARY	800.00	-
			6,380.00	1,630.00
	<b>GRAND TOTAL</b>		<b>47,468.25</b>	<b>7,988.38</b>

Report Ref No. CS/FCI22009801/Awy3m4



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			<b>6,400.00</b>
---	--	--	-----------------

Report Ref No. CS/FCI22009801/Awy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.