

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



DATE : 03.10.2022

TO : MS FIRST CAPITAL MOTOR CLAIMS DEPTS
VEHICLE NO : YQ193R
MODEL : HINO 300
DATE OF ACCIDENT : 03.10.2022
TIME OF ACCIDENT : 09:00 HRS

Xin Yu

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL LAMP RH canled	2	\$ 360.00	\$ 720.00
2	TAIL LAMP BRACKET RH Bent	2	\$ 186.50	\$ 373.00

360
186.50

546.5
409.87
TOTAL PRICE \$ 1,093.00
LESS 25% \$ 273.25
SUB TOTAL PRICE \$ 819.75

CLAIM DETAILS: SPECIAL NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE Bent	1	\$ 50.00	\$ 50.00
2	REAR NUMBER PLATE BRACKET Bent	1	\$ 198.50	\$ 198.50
3	REAR REINFORCEMENT New	1	\$ 2,800.00	\$ 2,800.00
4	REAR NUMBER PLATE LAMP New	1	\$ 120.00	\$ 120.00
5	REAR STEP BRACKET (WOODEN) canled	1	\$ 1,500.00	\$ 1,500.00
6	REAR CARGO BED REAR FRAME Reps	1	\$ 3,800.00	\$ 3,800.00
7	REAR CARGO BED BOTTOM BEAMS (WOODEN) 3 canled	9	\$ 1,500.00	\$ 13,500.00
8	CARGO BED CHASSIS MEMBER (WOODEN) New	2	\$ 6,500.00	\$ 13,000.00
9	CARGO BED U CLIP New	6	\$ 250.00	\$ 1,500.00
10	TAILGATE canled	1	\$ 3,800.00	\$ 3,800.00

✓
✓
+
+
1400
X.
7 1500.
+ 2000
X.
1800

5948.50 TOTAL \$ 40,268.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
-----	-----------------	-------	---------------

TO : **MS FIRST CAPITAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **YQ193R**
 MODEL : **HINO 300**
 DATE OF ACCIDENT : **03.10.2022**
 TIME OF ACCIDENT : **09:00 HRS**

1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 1,400.00	650.
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,000.00	300.
3	BULB CHECKING, WIRING	\$ 180.00	30.
4	REAR CHASSIS ALIGNMENT	\$ 200.00	X
5	REMOVE AND REFIX CARGO BED	\$ 2,800.00	650.
6	REMOVE AND REFIX CANOPY	\$ 800.00	X

1830

TOTAL \$ 6,380.00

TOTAL PARTS COST : \$ 41,088.25
 TOTAL LABOUR COST : \$ 6,380.00
 TOTAL REPAIR COST : \$ 47,468.25

Admin Lj
 L/s 04/10/22.
 05 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 7988.37
 L/s: 564K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: