



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009803/Acy3e2	
			Date: 23/06/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNB 5203Y	Veh. Inspected	SKZ 8324X
	Policy No.	D22MTPV01002417	Coverage (\$)	0.00
	Claim No.	CMTD2203543/AGC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	04/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	PEUGEOT 508	c.c	1560
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	VF38DBHZTFL043200	Colour	GREY
	Odometer	122174 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	NEXEN	6 mm
	L/H Front Tyre	215/55 R17	NEXEN	6 mm
	R/H Rear Tyre	215/55 R17	NEXEN	6 mm
	L/H Rear Tyre	215/55 R17	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	01/10/2022	Inspection Date	04/10/2022
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	