

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

Lee / Achuan

NG REN SHIN
 10 PRINSEP LINK #12-10
 SINGAPORE 187948

TAX INVOICE

Contact : 94504830, 81888418

Repair Code : CLM17403
 Date in : 03/10/2022
 Vehicle Num. : SKZ8324X
 Model : PEUGEOT 508 ALLURE 1.6 BLUEHDI EAT6
 Chassis/Eng# : VF38DBHZTFL043200/10JBHC3021411

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
AIR CLEANER RESONATOR BOX <i>changed</i>	1	265.00	✓ 265.00
AIRBAG CONTROL UNIT <i>Activated</i>	1	1720.00	1410 ✓ 1720.00
AIRCON CONDENSER <i>Distorted</i>	1	935.50	✓ 935.50
AIRCON CONDENSER AIR GUIDE GARNISH L/R <i>Distorted</i>	2	85.00	✓ 170.00
AIRCON CONDENSER DISCHARGE HOSE <i>Bent</i>	1	320.00	✓ 320.00
AIRCON CONDENSER LIQUID HOSE <i>new</i>	1	270.00	✗ 270.00
AIRCON CONDENSER RUBBER STOPPER L/R <i>new</i>	2	30.00	✓ 60.00
AIRCON CONDENSER RUBBER STOPPER LOCK CLIPS L/R <i>new</i>	2	25.00	✓ 50.00
AIRCON SUCTION HOSE <i>new</i>	1	370.00	✗ 370.00
BATTERY TOP COVER <i>new</i>	1	85.00	✗ 85.00
BATTERY TRAY <i>new</i>	1	120.00	✗ 120.00
ENGINE INTERCOOLER <i>Dented</i>	1	850.00	✓ 850.00
ENGINE INTERCOOLER INLET HOSE <i>new</i>	1	90.00	✗ 90.00
ENGINE INTERCOOLER OUTER HOSE <i>new</i>	1	85.00	✗ 85.00
EXHAUST MANIFOLD COVER (LOWER) <i>Dented</i>	1	100.00	✓ 100.00
EXHAUST MANIFOLD COVER (TOP)	1	105.00	✓ 105.00
FRONT BONNET <i>Distorted</i>	1	1680.00	✓ 1,680.00
FRONT BONNET CABLE GARNISH COVER <i>Damaged</i>	1	65.00	✓ 65.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

NG REN SHIN
 10 PRINSEP LINK #12-10
 SINGAPORE 187948

Contact : 94504830, 81888418

TAX INVOICE

Repair Code : CLM17403

Date in : 03/10/2022

Vehicle Num. : SKZ8324X

Model : PEUGEOT 508 ALLURE 1.6 BLUEHDI EAT6

Chassis/Eng# : VF38DBHZTFL043200/10JBHC3021411

FRONT BONNET DAMPER <i>Bent</i>	1	225.00	✓ 225.00
FRONT BONNET HINGES L/R <i>Bent</i>	2	130.00	✓ 260.00
FRONT BONNET INSULATOR MAT <i>Cracked</i>	1	450.00	✓ 450.00
FRONT BONNET LOCK <i>Turned</i>	1	95.00	✓ 95.00
FRONT BONNET LOCK CABLE <i>new</i>	1	100.00	X 100.00
FRONT BONNET OPENER HANDLE <i>Damaged</i>	1	75.00	✓ 75.00
FRONT BUMPER <i>Distorted</i>	1	1790.00	✓ 1,790.00
FRONT BUMPER CENTER PADDING <i>cracked</i>	1	382.00	✓ 382.00
FRONT BUMPER DAYLIGHT L/R <i>cracked</i>	2	990.00	1750.00 ✓ 1,980.00
FRONT BUMPER FOGLAMP COVER L/R <i>cracked</i>	2	155.00	✓ 310.00
FRONT BUMPER FOGLAMP L/R <i>cracked</i>	2	388.00	✓ 776.00
FRONT BUMPER INNER AIR VENT MODULE <i>cracked</i>	1	620.00	✓ 620.00
FRONT BUMPER INNER BRACKET <i>Damaged</i>	1	167.00	✓ 167.00
FRONT BUMPER INNER BRACKET L/R	2	120.00	✓ 240.00
FRONT BUMPER INNER FRAME GARNISH <i>Distorted</i>	1	168.00	✓ 168.00
FRONT BUMPER LOWER COVER <i>Not new</i>	1	205.00	X 205.00
FRONT BUMPER LOWER GRILLE <i>cracked</i>	1	370.00	✓ 370.00
FRONT BUMPER LOWER REINFORCEMENT <i>cracked</i>	1	205.00	✓ 205.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

NG REN SHIN
 10 PRINSEP LINK #12-10
 SINGAPORE 187948

Contact : 94504830, 81888418

TAX INVOICE

Repair Code : CLM17403

Date in : 03/10/2022

Vehicle Num. : SKZ8324X

Model : PEUGEOT 508 ALLURE 1.6 BLUEHDI EAT6

Chassis/Eng# : VF38DBHZTFL043200/10JBHC3021411

FRONT BUMPER PARKING SENSOR <i>new</i>	4	220.00	X	880.00
FRONT BUMPER PARKING SENSOR 'O' RING <i>new</i>	4	12.00	/	48.00
FRONT BUMPER PARKING SENSOR HOLDER BRACKET	6	35.00	/	210.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	65.00	/	130.00
FRONT BUMPER TOP REINFORCEMENT <i>Bent</i>	1	558.00	✓	558.00
FRONT BUMPER TOW HOOK COVER <i>new</i>	1	60.00	X	60.00
FRONT BUMPER WIRE HARNESS <i>new</i>	1	422.00	X	422.00
FRONT DASHBOARD <i>torn</i>	1	7480.00	<i>3950</i> 7,480.00	
FRONT DASHBOARD LH AIRBAG <i>Activated</i>	1	2130.00	✓	2,130.00
FRONT GRILLE <i>crushed</i>	1	412.00	✓	412.00
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	115.00	✓	115.00
FRONT GRILLE CENTER MOULDING <i>crushed</i>	1	300.00	✓	300.00
FRONT GRILLE CHROME MOULDING	1	380.00	✓	380.00
FRONT GRILLE UPPER TOP COVER <i>crushed</i>	1	272.00	✓	272.00
FRONT GRILLE UPPER TOP COVER RUBBER SEAL <i>new</i>	1	62.00	✓	62.00
FRONT HEADLAMP L/R <i>crushed</i>	2	1320.00	✓	2,640.00
FRONT HEADLAMP PANEL L/R <i>Bent</i>	2	170.00	✓	340.00
FRONT LH SEAT BELT BRACKET <i>new</i>	1	292.00	X	292.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

NG REN SHIN
 10 PRINSEP LINK #12-10
 SINGAPORE 187948

Contact : 94504830, 81888418

TAX INVOICE

Repair Code : CLM17403

Date in : 03/10/2022

Vehicle Num. : SKZ8324X

Model : PEUGEOT 508 ALLURE 1.6 BLUEHDI EAT6

Chassis/Eng# : VF38DBHZTFL043200/10JBHC3021411

FRONT SAFETY BELT L/R	<i>Activated</i>	2	750.00	✓	1,500.00
FRONT STEERING AIRBAG	<i>Activated</i>	1	2985.00	✓	2,985.00
FRONT STEERING AIRBAG CONTACT POINT	<i>Activated</i>	1	420.00	✓	420.00
FRONT SUPPORT PANEL	<i>Buckled</i>	1	590.00	✓	590.00
FRONT TOP PANEL	<i>Distorted</i>	1	215.00	✓	215.00
FRONT WINDSCREEN GLASS	<i>Shattered</i>	1	1620.00	✓	1,620.00
POWER STEERING COOLING OIL PIPE	<i>Bent.</i>	1	1400.00	<i>450</i> ✓	1,400.00
RADIATOR (A)	<i>Distorted</i>	1	965.00	✓	965.00
RADIATOR FAN MOTOR ASSY	<i>Cracked</i>	1	625.00	✓	625.00
RADIATOR FAN MOTOR RELAY UNIT	<i>Not new</i>	1	125.00	✗	125.00
RADIATOR LOWER HOSE	<i>Not in</i>	1	95.00	✗	95.00
RADIATOR RUBBER STOPPER CLIPS L/R	<i>2 Not</i>	2	25.00	✓	50.00
RADIATOR RUBBER STOPPER L/R		2	30.00	✓	60.00
RADIATOR TANK HOSE	<i>2 Not</i>	1	42.00	✗	42.00
RADIATOR TOP HOSE	<i>Not</i>	1	65.00	✗	65.00
WASHER TANK	<i>Not</i>	1	215.00	✗	215.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG REN SHIN
10 PRINSEP LINK #12-10
SINGAPORE 187948

Contact : 94504830, 81888418

TAX INVOICE

Repair Code : CLM17403

Date in : 03/10/2022

Vehicle Num. : SKZ8324X

Model : PEUGEOT 508 ALLURE 1.6 BLUEHDI EAT6

Chassis/Eng# : VF38DBHZTFL043200/10JBHC3021411

Subtotal before discount		43,461.50
Percentage discount 10%		4,346.15
Sub-total 1		39,115.35
FRONT BONNET INSULATOR MAT CLIPS - SET	1	50.00 30 50.00
FRONT GRILLE UPPER TOP COVER CLIPS - SET	1	50.00 20 50.00
FRONT NUMBER PLATE	1	35.00 ✓ 35.00
FRONT NUMBER PLATE HOLDER	1	50.00 30 50.00
FRONT WINDSCREEN GLASS E.R.P BRACKET	1	25.00 ✓ 25.00
FRONT WINDSCREEN GLASS E.R.P BRACKET STICKER	1	15.00 ✓ 15.00
FRONT WINDSCREEN GLASS MOULDING	1	100.00 ✓ 100.00
FRONT WINDSCREEN GLASS SEALANT	1	80.00 60 80.00
FRONT WINDSCREEN GLASS SOLAR FILM	1	380.00 200 380.00
POWER STEERING OIL	1	80.00 50 80.00
RADIATOR COOLANT	1	60.00 40 60.00
Subtotal before discount		925.00
Percentage discount 0%		0.00
Sub-total 2		925.00
Parts-total		40,040.35

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

NG REN SHIN
10 PRINSEP LINK #12-10
SINGAPORE 187948

Contact : 94504830, 81888418

TAX INVOICE

Repair Code : CLM17403

Date in : 03/10/2022

Vehicle Num. : SKZ8324X

Model : PEUGEOT 508 ALLURE 1.6 BLUEHDI EAT6

Chassis/Eng# : VF38DBHZTFL043200/10JBHC3021411

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

120 150.00

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.

380 500.00

To reset system after repair works

250 450.00

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

80 100.00

To remove, change windscreen.

120 150.00

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 100.00

To remove, change dashboard fascia and transfer where necessary.

250 450.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

850 1,000.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1000 1,200.00

To apply anti-rust chemical on repaired and replaced panel.

80 100.00

Labour Total

4,200.00

Parts & Labour Total

44,240.35

*** This is a computer-generated document which requires no signature.***

page 6

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

H/S : 28K
15 Days.