



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KHOR SAW THENG			Ref: CC4/ASM22009804/Rpa3q2 Date: 21/02/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SHA 7746K	<b>Veh. Inspected</b>	YQ 2249B
	<b>Policy No.</b>	P2465679	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	S2M04BQR	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	03/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HINO XZU710R 14FT WIDE	<b>c.c</b>	4009
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
	<b>Chassis No.</b>	JHHUCV3H60K033397	<b>Colour</b>	WHITE
	<b>Odometer</b>	92357 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	7.00 R16	BRIDGESTONE	7 mm
	<b>L/H Front Tyre</b>	7.00 R16	BRIDGESTONE	7 mm
	<b>R/H Rear Tyre</b>	7.00 R16 (D)	BRIDGESTONE	7/7 mm
	<b>L/H Rear Tyre</b>	7.00 R16 (D)	BRIDGESTONE	7/7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	22/09/2022	<b>Inspection Date</b>	04/10/2022
	<b>Survey held at</b>	SYSTEMATIC AIRCONDITIONING PTE LTD 29 SENOKO WAY SINGAPORE 758059		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	