

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009812/APA3Q2**Date:** 18/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700092129
Claimant Vehicle No :	SLG3930S	Insured Vehicle No :	EU9166B
Date of Loss:	24/09/2022	Nature of Claim:	TP
		Claim No:	2332558957SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG3930S	Engine No:	K9KG481D002296
Make & Model:	INFINITI Q30, 1.5 Premium (A)	Chassis No:	SJKDAAH15U1012578
Reg. Date:	29/09/2016 (Man. Year: 2016)	Odometer:	86552 km
Colour:	Black		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,312.23	7,492.29	4,819.94	39.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,130.00	1,550.00	57.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,992.23	8,622.29	6,369.94	42.49
Approved Total (Overridden) (S\$)		6,900.00		
(S\$)	14,992.23	6,900.00	8,092.23	53.98
+ GST 7.00/7.00% (S\$)	1,049.46	483.00	566.46	53.98
Nett Amount (S\$)	16,041.69	7,383.00	8,658.69	53.98
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,625.00		
Global Sum Settlement (S\$)		7,600.00		

INSPECTION

Date of Assignment:	27/09/2022	
Date Inspected:	27/09/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,964.50 FL	*1,380.00 FL
2	1		*REAR BUMPER LOWER LIP	Distorted	1,297.30 FL	*690.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	845.00 FL	*845.00 FL
4	1		*REAR BUMPER REINFORCEMENT SIDE BRACKET RH	Not Necessary	321.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Damaged	112.00 FL	*112.00 FL
6	1		*REAR BUMPER CENTER BRACKET	Cracked	54.00 FL	*54.00 FL
7	1		*REAR BUMPER REFLECTOR LAMP RH	Cracked	102.30 FL	*102.30 FL
8	1		*REAR BUMPER TOW COVER	Deformed	42.50 FL	*42.50 FL
9	2		*REAR BUMPER REVERSE SENSOR (1 SET OF 4 PCS)	Damaged	788.10 FL	*396.00 FL
10	1		*REAR BUMPER REVERSE SENSOR BRACKET	Necessary	54.00 FL	*54.00 FL
11	1		*REAR BUMPER REVERSE SENSOR WIRE	Not Necessary	478.00 FL	*- FL
12	1		*REAR END PANEL	Repair	999.10 FL	*- FL
13	1		*REAR TAILLAMP RH	Cracked	933.10 FL	*752.00 FL
14	1		*REAR BOOTLID	Dented	3,790.20 FL	*2,980.00 FL
15	1		*REAR BOOTLID EMBLEM LOGO	Necessary	78.40 FL	*78.40 FL
16	1		*REAR BOOTLID EMBLEM Q30	Necessary	65.10 FL	*65.10 FL
17	1		*REAR BOOTLID LAMP RH	Not Necessary	579.30 FL	*- FL
18	1		*REAR EXHAUST TAIL PIPE	Damaged	367.00 FL	*367.00 FL
19	1		*REAR EXHAUST TAIL PIPE TOP GARNISH	Deformed	32.80 FL	*32.80 FL
20	1		*EXHAUST ALUMINIUM SHIELD	Crumpled	132.00 FL	*132.00 FL
21	1		*RH FENDER INNER COWLING	Torn	195.00 FL	*195.00 FL
22	1		*RH FENDER OUTER PROTECTOR	Not Necessary	214.00 FL	*- FL
23	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR TAILLAMP CLIPS RH	Necessary	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,656.70	8,320.10
- List Item Discount on L Items 10.00/10.00% (S\$)	1,344.47	827.81
Total Parts (S\$)	12,312.23	7,492.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,400.00	500.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	600.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & RENEW REAR EXHAUST TAIL PIPE /TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE	New	200.00	0.00
Gross Labour Cost (\$\$)			2,680.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >