

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM\_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date : 04/01/2022

Estimated repair cost for vehicle no: SLG 3930S INFINITI Q30 1.5D PREMIUM DCT

CHASSIS: SJKDAAH15U1012578 (2016)

| S/N | Qty | Items                                                              | U/price              | Amount                 |
|-----|-----|--------------------------------------------------------------------|----------------------|------------------------|
| 1   | 1   | REAR BUMPER <i>Distorted</i>                                       | \$1,964.50           | \$1,964.50 ✓           |
| 2   | 1   | REAR BUMPER LOWER LIP <i>Distorted</i>                             | \$1,297.30           | \$1,297.30 ✓           |
| 3   | 1   | REAR BUMPER REINFORCEMENT <i>Distorted</i>                         | \$845.00             | \$845.00 ✓             |
| 4   | 1   | REAR BUMPER REINFORCEMENT SIDE BRACKET RH <i>Broken</i>            | \$321.00             | \$321.00 ✗             |
| 5   | 1   | REAR BUMPER SIDE RETAINER RH <i>Distorted</i>                      | \$112.00             | \$112.00 ✓             |
| 6   | 1   | REAR BUMPER CENTER BRACKET <i>crushed</i>                          | \$54.00              | \$54.00 ✓              |
| 7   | 1   | REAR BUMPER REFLECTOR LAMP RH <i>crushed</i>                       | \$102.30             | \$102.30 ✓             |
| 8   | 1   | REAR BUMPER TOW COVER <i>Distorted</i>                             | \$42.50              | \$42.50 ✓              |
| 9   | 1   | REAR BUMPER REVERSE SENSOR (1 SET OF 4 PCS) <i>2 pieces broken</i> | \$788.10             | \$788.10 396 ✗         |
| 10  | 1   | REAR BUMPER REVERSE SENSOR BRACKET <i>new</i>                      | \$54.00              | \$54.00 ✓              |
| 11  | 1   | REAR BUMPER REVERSE SENSOR WIRE <i>new</i>                         | \$478.00             | \$478.00 ✗             |
| 12  | 1   | REAR END PANEL <i>Revised</i>                                      | \$999.10             | \$999.10 ✗             |
| 13  | 1   | REAR TAILLAMP RH <i>crushed</i>                                    | \$933.10             | \$933.10 752 ✗         |
| 14  | 1   | REAR BOOTLID <i>Distorted</i> 2980                                 | <del>\$3790.20</del> | <del>\$3790.20</del> ✗ |
| 15  | 1   | REAR BOOTLID EMBLEM Q30 <i>3 pcs</i>                               | \$65.10              | \$65.10 ✓              |
| 16  | 1   | REAR BOOTLID EMBLEM LOGO                                           | \$78.40              | \$78.40 ✓              |
| 17  | 1   | REAR BOOTLID LAMP RH <i>new</i>                                    | \$579.30             | \$579.30 ✗             |
| 18  | 1   | REAR EXHUAUST TAIL PIPE <i>Damaged</i>                             | \$367.00             | \$367.00 ✓             |
| 19  | 1   | REAR EXHUAUST TAIL PIPE TOP GARNISH <i>Distorted</i>               | \$32.80              | \$32.80 ✓              |

- Supplementary.
- ① Exhaust Aluminium shield - *crushed* ✓ 132
  - ② RM Bumper inner cowling - *torn* ✓ 195
  - ③ RM Fender outer protector - *new* x 214.

TOTAL : \$9,113.50  
 LESS 10 % \$911.35  
 SUB-TOTAL : \$8,202.15

8278.10  
 7450.29

## SLG 3930S INFINITI Q30

| S/N | Qty | ITEMS / SPECIAL NETT              | U/price  | Amount            |
|-----|-----|-----------------------------------|----------|-------------------|
| 1   | 1   | REAR BUMPER CLIPS <i>per</i>      | \$80.00  | \$80.00 <i>30</i> |
| 2   | 1   | REAR END PANEL SEALANT <i>per</i> | \$120.00 | \$120.00 <i>4</i> |
| 3   | 1   | REAR TAILLAMP CLIPS RH <i>per</i> | \$12.00  | \$12.00 <i>✓</i>  |

42

TOTAL: \$212.00TOTAL PARTS: \$8,414.15Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & RENEW REAR EXHAUST TAIL PIPE / TO REPAIR & STRAIGHTEN REAR EXHUAST PIPE

1130

*500*  
\$1,400.00*600*  
\$1,000.00*30*  
\$80.00*+*  
\$200.00Subtotal :- \$2,680.00Total:- \$11,094.15*Admin*  
*h/s 27/09/22.**04 days.**bill. 862229.**L/S: 69K.**69K.*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: