

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SJY 419 B

Chassis No: WAUZZZ8F2AN023047

Make/Model : AUDI A5

Accident date : 28.09.2022

TP chin.

Xiao Kong.

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear bootlid <i>Dented.</i>	1	\$ 3859 ✓
2	Rear bootlid hinges @ \$ 129 <i>Ne m</i>	2	\$ 258 +
3	Rear bootlid upper lock <i>Dented</i>	1	\$ 298 ✓
4	Rear bootlid lower lock <i>Ne m</i>	1	\$ 41 x.
5	Rear bootlid shock absorber @ \$ 190 <i>Ne m</i>	2	\$ 380 x.
6	Rear bootlid weather strip <i>lt</i>	1	\$ 282 ✓
7	Rear bootlid top spoiler <i>Ne m</i>	1	\$ 680 +
8	Rear bootlid centre logo	1	\$ 115 ✓
9	Rear bootlid "A5" emblem <i>Ne m</i>	1	\$ 88 ✓
10	Rear bootlid "2.0T" emblem (set)	1	\$ 78 ✓
11	Rear bootlid "ABT" emblem	1	\$ 82 ✓
12	Rear bootlid reflector @ \$ 864 <i>2H could.</i>	2	\$ 1728 864
13	Rear bootlid insulation <i>Ne m</i>	1	\$ 320 +
14	Rear lamp @ \$ 1081 <i>1H could.</i>	2	\$ 2162 1081
15	Rear lamp housing @ \$ 314 <i>Repair</i>	2	\$ 628 +
16	Rear end panel <i>Distorted.</i>	1	\$ 932 ✓
17	Rear end panel top garnish <i>Deformed</i>	1	\$ 241 ✓
18	Rear bumper <i>Distorted</i>	1	\$ 2474 ✓
19	Rear bumper side holder @ \$ 91 <i>Dnd</i>	2	\$ 182 ✓
20	Rear bumper reinforcement <i>Dented</i>	1	\$ 885 ✓
21	Rear bumper bracket @ \$ 75 <i>Bent</i>	2	\$ 150 ✓
22	Rear bumper lower lip <i>Distorted</i>	1	\$ 307 ✓
23	Rear LH fender inner shield <i>torn</i>	1	\$ 225 ✓
24	Rear LH fender inner trim <i>Ne m</i>	1	\$ 731 x.
25	Rear LH exhaust pipe <i>Bent.</i>	1	\$ 1190 ✓
26	Rear LH exhaust pipe chrome <i>Bent</i>	1	\$ 120 ✓
27	Rear LH exhaust pipe top cover <i>Crushed</i>	1	\$ 205 ✓
28	Rear LH exhaust pipe bracket <i>Ne m</i>	1	\$ 48 x.
29	Rear LH exhaust mounting <i>Ne m</i>	1	\$ 35 x.
30	Rear spare tyre top board <i>Ne m</i>	1	\$ 786 +
31	Rear bootlid lock sensor <i>Ne m</i>	1	\$ 241 +
32	Rear LH air vent <i>Ne m</i>	1	\$ 63 x
			\$ 19,754.00
Less 10% Disc			\$
Total			\$ 17,778.60

12619
11357.10

13658
12292.20

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Vehicle No : SJY 419 B

Make/Model : AUDI A5

Chassis No: WAUZZZ8F2AN023047

Accident date : 28.09.2022

No	DESCRIPTION	Qty	Amount (\$\$)
Special Nett Items			
1	Rear bumper reverse sensor @ \$ 260. <i>3 pieces dmd</i>	4	\$ 1040. <i>780.</i>
2	Rear number plate <i>3 NP</i>	1	\$ 50.00 <i>+</i>
3	Rear number plate holder <i>1 new</i>	1	\$ 50.00 <i>+</i>
		Total	\$ 1,140.00

Labour Cost			
1	Towing fee		\$ 150.00 <i>120.</i>
2	To check wiring		\$ 100.00 <i>30</i>
3	To <i>perform diagnostic test</i>		\$ 100.00 <i>✓</i>
4	Remove & reinstall bootlid inner trim		\$ 200.00 <i>80</i>
5	Remove & reinstall exhaust pipe		\$ 400.00 <i>160.</i>
6	Remove & refix reverse sensor		\$ 200.00 <i>60.</i>
7	Remove ,replace & repair consistent to the accident		\$ 1,500.00 <i>1000.</i>
8	Respray painting		\$ 1,400.00 <i>1000.</i>
9	Tuff kote		\$ 100.00 <i>80.</i>
		Total	\$ 4,150.00

Grand Total \$ 23,068.60

total: 15702.60

L/S: 12.5K

08 Days.

12.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: