

Zhong Cheng Enterprise Pte Ltd - Woodlands (Co.Reg.No:201611525M)
BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE
Singapore 678008
Tel: 67694686 Email: zhongchengauto@gmail.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC22B00032000	Date of Loss:	24/09/2022
Vehicle Reg. No.:	SNB3994K	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ONG KENG BOON		
Driver:	ONG KENG BOON		
Make/Model:	TOYOTA NOAH, 1.8 (A)	Vehicle Reg. Date:	19/08/2021
Vehicle Colour:	Black		
Engine No:	2ZR2M86676	Chassis No:	ZWR800507003
Odometer:	27786 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	ZHONG CHENG ENTERPRISE PTE LTD - WOODLANDS (HQ)		

COST OF CLAIMS

	Amount
Parts	8,305.00
Miscellaneous Items	661.00
Labour	1,410.00
Paintwork Labour	900.00
Towing	0.00
Nett Amount (S\$)	11,276.00

This claim is handled by: TAN SINI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Oct 2022)
 Parts: M1-MPV TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Zhong Cheng Enterprise Pte Ltd - Woodlands/SNB3994K/02/10/2022 22:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Air-cond condenser <i>75/</i>	0.00	0.00	*495.00 F
2	1		Bumper bracket LH, front <i>? cm</i>	0.00	0.00	*30.00 F
3	1		Bumper bracket RH, front <i>? cm</i>	0.00	0.00	*30.00 F
4	1		Bumper protector center, front <i>? cm</i>	0.00	0.00	*95.00 F
5	1		Bumper reinforcement, front <i>? X 11</i>	0.00	0.00	*185.00 F
6	1		Bumper, front <i>cm</i>	0.00	0.00	*290.00 F
7	1		Headlamp LH <i>cm</i>	0.00	0.00	*950.00 F
8	1		Headlamp RH <i>cm</i>	0.00	0.00	*950.00 F
9	1		Panel, front <i>bt</i>	0.00	0.00	*600.00 F
10	1		Radiator <i>? bt</i>	0.00	0.00	*550.00 F
11	1		W/screen glass moulding, front <i>new</i>	0.00	0.00	*400.00 F
12	1		W/screen glass, front <i>cm</i>	0.00	0.00	*85.00 F
13	1		*Fender LH, front <i>bt</i>	0.00	0.00	*330.00 F
14	1		*Fender RH, front <i>bt</i>	0.00	0.00	*330.00 F
15	1		*GRILLE LOGO EMBLEM FRONT <i>scu</i>	0.00	0.00	*55.00 F
16	1		*GRILLE-RADIATOR <i>cm</i>	0.00	0.00	*390.00 F
17	1		*Bonnet <i>bt</i>	0.00	0.00	*380.00 F
18	1		*Bonnet lock lower <i>bt</i>	0.00	0.00	*90.00 F
19	1		*BRACE PANEL FRONT <i>bt</i>	0.00	0.00	*95.00 F
20	1		*GRILLE UPPER <i>cm</i>	0.00	0.00	*360.00 F
21	1		*Fender bracket LH, front <i>new</i>	0.00	0.00	*20.00 F
22	1		*Fender bracket RH, front <i>new</i>	0.00	0.00	*20.00 F
23	1		*Horn <i>scu</i>	0.00	0.00	*120.00 F
24	1		*FENDER INNER TRIM LH <i>X 11</i>	0.00	0.00	*90.00 F
25	1		*FENDER INNER TRIM RH <i>X 11</i>	0.00	0.00	*90.00 F
26	1		*FENDER INNER TRIM RH CLIPS <i>new</i>	0.00	0.00	*20.00 F
27	1		*FENDER INNER TRIM LH CLIPS <i>new</i>	0.00	0.00	*20.00 F
28	1		*FOG LAMP LH <i>X 11</i>	0.00	0.00	*60.00 F
29	1		*FOG LAMP RH <i>X 11</i>	0.00	0.00	*60.00 F
30	1		*Headlamp bracket RH <i>? X 11</i>	0.00	0.00	*80.00 F
31	1		*Headlamp bracket LH <i>? X 11</i>	0.00	0.00	*80.00 F
32	1		*SENSOR, FRONT <i>X 11</i>	0.00	0.00	*200.00 F

F=Franchise part.

Sub Total (\$\$)	7,550.00
+ Margin on L,N Items 10.00% (\$\$)	755.00
Total Parts (\$\$)	8,305.00

Zhong Cheng Enterprise Pte Ltd - Woodlands/SNB3994K/02/10/2022 22:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Air-cond gas (R134A) <i>✓</i>	60.00 40
2	1	AIRCON COOLANT <i>✓</i>	30.00
3	1	GST <i>X</i>	528.50 <i>X</i>
4	1	Windscreen sealant, front <i>✓</i>	42.50
Sub Total (S\$)			661.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	PUTTY/ SPRAY PAINT & POLISHING	New	900.00 800
<u>Labour Items</u>			
2	PANEL BEATING/ DISMANTLE & REFIX	New	900.00 800
3	DISMANTLE/ REFIX WINDSCREEN	New	100.00
4	DISMANTLE/REFIX AIRCON CONDENSER & RADIATOR	New	160.00 120
5	RESET FAULT CODE	New	200.00 100
6	REMOVE/REFIX FRONT SENSOR	New	50.00 11 X
Gross Labour Cost (S\$)			2,310.00

Zhong Cheng Enterprise Pte Ltd - Woodlands/SNB3994K/02/10/2022 22:46. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068
8 days
L/S
05/10/22 @ 1550
EXCESS: 500
Revert
Resy after repair