



**Bedok Motor Engineering Pte Ltd**  
30 Defu Lane 9 Singapore 539270  
<http://www.bedokmotor.com>  
[enquire@bedokmotor.com](mailto:enquire@bedokmotor.com)  
+65 6286 3032

**Estimate To Repair CB7551J NISSAN / URVAN 3.0 M**

Chassis No : JN1TG4E25Z0702294

| S/No                            | Quantity | Description                                                        | Amount      |
|---------------------------------|----------|--------------------------------------------------------------------|-------------|
| <u>LIST ITEMS</u>               |          |                                                                    |             |
| 1                               | 1pc      | Right side body panel assy                                         | \$ 1,989.50 |
| 2                               | 1pc      | Rear bumper assy                                                   | \$ 349.50   |
|                                 |          |                                                                    | \$ 2,339.00 |
| Less 20%                        |          |                                                                    | \$ 467.80   |
|                                 |          |                                                                    | \$ 1,871.20 |
| <u>SPECIAL NETT ITEAMS</u>      |          |                                                                    |             |
|                                 |          |                                                                    | \$ -        |
| <u>LABOUR &amp; MISC CHARGE</u> |          |                                                                    |             |
| 1                               |          | Spray Painting.                                                    | \$ 1,400.00 |
| 2                               |          | To remove and refit cctv camera.                                   | \$ 400.00   |
| 3                               |          | To remove and renew the above parts , adjust and realign the same. | \$ 1,200.00 |
|                                 |          |                                                                    | \$ 3,000.00 |
| P/P \$1000 and 4 days           |          |                                                                    |             |
| <del>4/5,1000</del>             |          |                                                                    |             |
| Total                           |          |                                                                    | \$ 4,871.20 |

4 Days.

Lumpsum mpr

After mpr photos.

Gmo Qian - 8288 0282

CLKK)

5/10/22.

BedokMotor : 81838432

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: