



Bedok Motor Engineering Pte Ltd
 30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
 +65 6286 3032

Estimate To Repair CB7551J NISSAN / URVAN 3.0 M

Chassis No : JN1TG4E25Z0702294

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
1	1pc	Right side body panel assy	\$ 1,989.50
2	1pc	Rear bumper assy	\$ 349.50
			\$ 2,339.00
		Less 20%	\$ 467.80
			\$ 1,871.20
		<u>SPECIAL NETT ITEAMS</u>	
			\$ -
		<u>LABOUR & MISC CHARGE</u>	
1		Spray Painting.	\$ 1,400.00
2		To remove and refit cctv camera.	\$ 400.00
3		To remove and renew the above parts , adjust and realign the same.	\$ 1,200.00
			\$ 3,000.00
		Total	\$ 4,871.20