



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Estimate To Repair CB7551J NISSAN / URVAN 3.0 M

Chassis No : JN1TG4E25Z0702294

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Right side body panel assy	\$ 1,989.50
2	1pc	Rear bumper assy	\$ 349.50
			\$ 2,339.00
Less 20%			\$ 467.80
			\$ 1,871.20
<u>SPECIAL NETT ITEAMS</u>			
			\$ -
<u>LABOUR & MISC CHARGE</u>			
1		Spray Painting.	\$ 1,400.00
2		To remove and refit cctv camera.	\$ 400.00
3		To remove and renew the above parts , adjust and realign the same.	\$ 1,200.00
			\$ 3,000.00
Total			\$ 4,871.20

4 Days.

Lumpsum mpr

After mpr photos.

Gmo Qian - 8288 0282

CLKK)

5/10/22.

BedokMotor : 81838432

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: