



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009828/Acy3e2	
			Date: 03/04/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBS 3746M	Veh. Inspected	SNG 4754D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203534/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA C-HR HYBRID	c.c	1797
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	ZYX102111985	Colour	SILVER
	Odometer	72871 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R17	TOURADOR	6 mm
	L/H Front Tyre	215/60 R17	TOURADOR	6 mm
	R/H Rear Tyre	215/60 R17	TOURADOR	6 mm
	L/H Rear Tyre	215/60 R17	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/10/2022	Inspection Date	05/10/2022
	Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	