

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 30/09/2022

Estimated repair cost for vehicle no: SLT2867E TOYOTA HARRIER G GRADE

CHASSIS: JTEKB3GH50J000484 (2017)

03/10/2022

S/N	Qty	Items	U/price	Amount
1	1	LH FRONT FENDER <i>Repair</i>	\$1,025.30	\$1,025.30 <i>+</i>
2	1	LH FRONT DOOR <i>Dented</i>	\$1,881.30	\$1,881.30 <i>✓</i>
3	1	LH FRONT DOOR OUTER CHROME MOULDING <i>cut</i>	\$168.70	\$168.70 <i>✓</i>
4	1	LH FRONT DOOR INNER TRIM BOARD <i>new</i>	\$512.90	\$512.90 <i>+</i>
5	2	LH FRONT DOOR HINGE <i>new</i>	\$58.90	\$117.80 <i>+</i>
6	1	LH FRONT DOOR CHECKER <i>new</i>	\$62.30	\$62.30 <i>+</i>
7	1	LH FRONT DOOR LOCK <i>new</i>	\$338.40	\$338.40 <i>✓</i>
8	1	LH FRONT DOOR WEATHER STRIPE <i>new</i>	\$198.10	\$198.10 <i>+</i>
9	1	LH FRONT DOOR POWER WINDOW MOTOR <i>new</i>	\$689.70	\$689.70 <i>+</i>
10	1	LH FRONT DOOR POWER WINDOW GEAR <i>new</i>	\$588.70	\$588.70 <i>315</i>
11	1	LH FRONT DOOR OUTER HANDLER WITH SENSOR <i>cut</i>	\$361.40	\$361.40 <i>✓</i>
12	1	LH FRONT DOOR WIND MIRROR <i>cut</i>	\$1,230.10	\$1,230.10 <i>✓</i>
13	1	LH FRONT DOOR WIND MIRROR COVER <i>Repair</i>	\$112.80	\$112.80 <i>+</i>
14	1	LH ROCKER PANEL GARNISH <i>Dented</i>	\$1,021.10	\$1,021.10 <i>645</i>
15	1	LH REAR DOOR <i>Dented</i>	\$1,882.10	\$1,882.10 <i>1745</i>
16	1	LH REAR DOOR OUTER CHROME MOULDING <i>cut</i>	\$168.80	\$168.80 <i>✓</i>
17	1	LH REAR DOOR INNER TRIM BOARD <i>cut & new</i>	\$512.90	\$512.90 <i>✓</i>
18	2	LH REAR DOOR HINGE <i>new</i>	\$58.90	\$117.80 <i>+</i>
19	1	LH REAR DOOR CHECKER	\$62.30	\$62.30 <i>+</i>
20	1	LH REAR DOOR LOCK <i>new</i>	\$338.40	\$338.40 <i>+</i>
21	1	LH REAR DOOR WEATHER STRIPE <i>new</i>	\$198.10	\$198.10 <i>+</i>
22	1	LH REAR DOOR POWER WINDOW MOTOR <i>new</i>	\$689.70	\$689.70 <i>+</i>
23	1	LH REAR DOOR POWER WINDOW GEAR <i>new</i>	\$588.70	\$588.70 <i>325</i>
24	1	LH REAR DOOR OUTER HANDLER WITH SENSOR <i>cut</i>	\$361.40	\$361.40 <i>✓</i>
25	1	LH REAR FENDER <i>Repair</i>	\$2,243.10	\$2,243.10 <i>+</i>
26	1	REAR WINDSCREEN GLASS MOULDING <i>new</i>	\$178.40	\$178.40 <i>+</i>
27	1	LH REAR SHOCK ABSORBER <i>new</i>	\$731.20	\$731.20 <i>+</i>
28	1	LH REAR ADJUSTER ARM <i>new</i>	\$711.20	\$711.20 <i>+</i>
29	1	LH REAR KNUCKLER ARM <i>Damaged</i>	\$631.10	\$631.10 <i>✓</i>
30	1	LH REAR KNUCKLER ARM BEARING <i>new</i>	\$580.10	\$580.10 <i>✓</i>
31	1	LH REAR UPPER ARM <i>new</i>	\$789.10	\$789.10 <i>+</i>

TP Chinn.

Xiao Tong.

JTEKB3GH50J000484

SLT2867E TOYOTA HARRIER

32	1	LH REAR LOWER ARM <i>sent</i>	\$570.90	\$570.90 ✓
----	---	-------------------------------	----------	------------

9972.50

7479.37

TOTAL :	\$19,287.90
LESS 25 %	\$4,821.98
SUB-TOTAL :	\$14,465.93

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	LH FRONT SPORT RIM <i>cut</i>	\$1,400.00	\$1,400.00 1100
2	1	LH REAR SPORT RIM <i>cut</i>	\$1,400.00	\$1,400.00 1100
3	1	LH FRONT DOOR INNER TRIM BOARD CLIPS <i>3/10</i>	\$80.00	\$80.00 30
4	1	LH REAR DOOR INNER TRIM BOARD CLIPS	\$80.00	\$80.00 30
5	1	LH ROCKER PANEL GARNISH CLIPS <i>new</i>	\$80.00	\$80.00 30

2290

TOTAL:	\$3,040.00
---------------	-------------------

TOTAL PARTS:	\$17,505.93
---------------------	--------------------

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 LABOUR FOR REMOVE & REMOVE & REFIX WINDSCREEN GLASS
- 5 LABOUR FOR REMOVE & TRANSFER BOTH LH DOOR FITTING
- 6 LABOUR FOR REMOVE & REFIX LH INNER TRIM BOARD/UPHOLSTERY
- 7 LABOUR FOR REMOVE & RENEW LH REAR UNDER CARRIAGE
- 8 TO CONDUCT WHEEL ALIGNMENT

2090

\$2,000.00 <i>800</i>
\$1,800.00 <i>800</i>
\$80.00 <i>30</i>
\$150.00 <i>x</i>
\$300.00 <i>160</i>
\$300.00 <i>x</i>
\$400.00 <i>220</i>
\$150.00 <i>80</i>

Subtotal :-	\$5,180.00
--------------------	-------------------

Total:-	\$22,685.93
----------------	--------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lhl: 11859.37

L/8 9.5K

(9.5K)

Adrian L
r/s 03/10/22

06 Days.