



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CS3/CTI22006958/Avy3e2-1 Date: 13/10/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMG 8969L	Veh. Inspected	SKK 1248H
Policy No.	DMPCSNW00005492201	Coverage (\$)	0.00
Claim No.	SNM22D205041/C02/TANCHC	Excess (\$)	0.00
Assign From	JACQUELINE TAN	Assign Date	03/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY	c.c	2487
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	AXVH701046628	Colour	BLACK
Odometer	44963 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/45 R18	GOODYEAR	6 mm
L/H Front Tyre	235/45 R18	GOODYEAR	6 mm
R/H Rear Tyre	235/45 R18	GOODYEAR	6 mm
L/H Rear Tyre	235/45 R18	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/07/2022	Inspection Date	21/07/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	