

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display on the repairer's (s) website
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurer's company

Acknowledged by Repairer

Signature:

Date:

Vehicle No : SLX 5301 E

Chassis No: WVVZZZ13ZBV015397

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WVVZZZ13ZBV

TPAXA

Xiao Tony
015397

Make/Model : VOLKSWAGEN SCIROCCO

Accident date : 24.09.2022

No	DESCRIPTION	Qty	Amount (\$S)
List Items			
1	Front bumper <i>Deformed.</i>	1	\$ 1,869.80
2	Front bumper side holder @ \$120.80 <i>LH Danged.</i>	2	\$ 241.60
3	Front bumper LH lower lip <i>Repair</i>	1	\$ 990.40
4	Front bumper LH fod lamp	1	\$ 317.00
5	Front bumper LH fod lamp cover <i>Not new</i>	1	\$ 331.10
6	Front bumper LH side lamp	1	\$ 257.40
7	Front LH headlamp <i>At</i>	1	\$ 991.10
8	Front LH fender <i>Danted.</i>	1	\$ 991.10
9	Front LH fender inner shield <i>Deformed.</i>	1	\$ 427.90
10	Front LH fender APR sticker <i>Not new</i>	1	\$ 85.00
11	Front LH fender inner rear garnish <i>Not new</i>	1	\$ 250.00
12	Front LH door <i>Repair</i>	1	\$ 3,310.70
13	Front LH shock absorber <i>Bent.</i>	1	\$ 1,099.70
14	Front LH lower arm <i>Bent.</i>	1	\$ 650.00
15	Front LH drive shaft <i>Not new</i>	1	\$ 2,639.70
16	Front LH knuckle arm <i>Bent</i>	1	\$ 1,473.60
17	Front LH knuckle arm bearing <i>Bent</i>	1	\$ 1,099.70
18	Front LH linkage <i>Not new</i>	1	\$ 208.90
19	Steering rack assy <i>Bent.</i>	1	\$ 7,578.60
			\$ 24,813.30
			Less 10% Disc \$ 2,481.33
			Total \$ 22,331.97

Special Nett Items

1	Front LH sport rim <i>Cracked.</i>	1	\$ 900.00
2	Front LH tyre <i>Punctured.</i>	1	\$ 400.00
3	Front LH fender inner shield clips (1 set) <i>new</i>	1	\$ 50.00
4	Front bumper clips (1 set) <i>new</i>	1	\$ 50.00
			Total \$ 1,400.00

Labour Cost

1	Towing fee		\$ 150.00
2	To check wheel alignment		\$ 100.00
3	Remove & reinstall front undercarriage		\$ 600.00
4	Remove ,replace & repair consistent to the accident		\$ 1,300.00
5	Respray painting		\$ 1,200.00
6	Tuff kote		\$ 100.00
			Total \$ 3,450.00

Grand Total \$ 27,181.97

9.81K

total 12264.69
4/5 9.81K 05Days