

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En A	utomol	bile CS3/ASM22005401/Tgy3
	AXA INSURANCE			ef:	C33/A3M22005401/Tqc
	8 SHENTON WAY AXA TOWERSING		D	ate:	<del>07/80/2822</del> 02/10/2022
			C	ode:	ASM
	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 7969J	Veh. Inspected		FBT 15D
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M043FX	Excess (\$)		0.00
	Assign From	KHOR OW Theng NYI (SEAH ONG)	Assign Date		<del>07/00/2022</del> 02/10/2022
•	TENG AII	Vehicle Parti	culars & Condition	า	
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	Steering			
	Brakes	Modification			
	General				
	_	Condit	ions of Tyres		
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
	Description of Damages				
General Information					
	Accident Date	03/06/2022	Inspection Date		07/06/2022
	Survey held at	ADVANCE REPUBLIC PTE LTI			
		BLK 68 KAKI BUKIT AVE 6 #04-06 SINGAPORE 417896			
a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				