



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBT 15D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	NEW NUMBER PLATE	DAMAGED	35.00	20.00
1	NEW REAR BOTTOM BRACKET	NOT NECESSARY	150.00	-
			185.00	20.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REPLACE, REPAIR AND STRAIGHTEN THE ABOVE DAMAGED PARTS. TO RE-ADJUST TO THE ORIGINAL POSITION.		380.00	200.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		150.00	150.00
	TO PROVIDE TRANSPORT SERVICE CHARGE.		80.00	40.00
			610.00	390.00
	<b>GRAND TOTAL</b>		<b>795.00</b>	<b>410.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>410.00</b>

Report Ref No. CS3/ASM22005401/Tqy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.