

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	24 BENOI SECTOR
CONTACT NO	:	6474 3323
FAX NO	:	6264 6786
REFERENCE	:	PAC/OD/0072/2022/GW
DATE	:	4-Oct-22
WIP	:	

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

ALLIANZ INSURANCE SINGAPORE PTE LTD
79 Robinson Road
#09-01
Singapore 068897

ATTN: MOTOR CLAIMS DEPT
Tel: 6297 2529 Fax: 6297 1956

OWNER'S NAME	:	MS LOW KIAN MIN
ADDRESS	:	567 REVOSE CRESCENT #04-05 SINGAPORE 298088
TELEPHONE	:	HP +65 97570453
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	SP2001838745-01
VEHICLE NO	:	SLP 5813 L
MODEL CODE	:	AUDI A4 1.4 TFSI
MODEL YEAR	:	9/6/2017
ENGINE NO	:	CVN038943
CHASSIS NO	:	WAUZZZF46HA163802
MILEAGE	:	-
DATE IN	:	
ESTIMATED BY	:	ALLAN WU
ACCIDENT DATE	:	30-Sep-22
PLACE OF ACCIDENT	:	DUNEARN RD & WHITLEY RD

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 5813 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 150.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	\$ 200.00	?
3	TO REMOVE AND RENEW AIR CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT, PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N	\$ 400.00	?
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N	\$ 200.00	✓
SUB -TOTAL LABOUR CHARGES		:	\$ 950.00	

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 5813 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. <i>Bonnet 2x 200</i>	\$ 1,600.00	<i>400</i>
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HIGENS, BOTH FRONT DOOR AND BOTH UPPER A - PILLAR. <i>2 4x 200</i>	\$ 1,800.00	<i>800</i>
7	TO CARRY OUT DIAGNOSTI CHECK.	S/N \$ 150.00	<i>/</i>
TOTAL LABOUR CHARGES		: \$ 4,500.00	

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
 TEL : 6474 3323 FAX : 6264 6786
 EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5813 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT	
				COST + 10 %
1 FRONT BUMPER / <i>MD</i>	1	\$	2,377.00	
2 FRONT BUMPER FIXING PARTS <i>X</i>	1		TBC	
3 FRONT BUMPER SECURING STRIP <i>?</i>	2	\$	79.00	
4 FRONT BUMPER GRILLE - CENTER <i>?</i>	1	\$	219.00	
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$	254.00	
6 RADIATOR AIR GUIDE - LH / RH <i>?</i>	2	\$	144.00	
7 RADIATOR GRILLE - <i>BR</i>	1	\$	1,277.00	
8 FRONT AIR GUIDE GRILLE - LH <i>?</i>	1	\$	151.00	
9 FRONT AIR GUIDE GRILLE - RH <i>?</i>	1	\$	151.00	
10 FRONT FOAM FILLER PIECE <i>?</i>	1	\$	139.00	
11 FRONT REINFORCEMENT BEAM <i>?</i>	1	\$	899.00	
12 FRONT BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$	82.00	
13 FRONT BUMPER COVER - <i>BR</i>	1	\$	143.00	
14 FRONT REINFORCEMENT BEAM BRACKET - LH / RH <i>?</i>	2	\$	508.00	
15 SIGN CAUTION STICKER - <i>MC</i>	1	\$	16.00	
16 AIR CONDITIONER STICKER - <i>MC</i>	1	\$	9.00	
17 FRONT LOCK CARRIER BRACKET - <i>BR</i>	1	\$	154.00	
18 FRONT LOCK CARRIER SUPPORT - LH / RH	2	\$	64.00	
19 POP RIVET <i>?</i>	4	\$	4.00	
20 FRONT FANFARE - LH <i>X</i>	1	\$	134.00	
SUB - TOTAL PARTS CHARGES	:	\$	6,804.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
 TEL : 6474 3323 FAX : 6264 6786
 EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5813 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
				COST + 10 %
21 FRONT FANFARE - RH X	1	\$	139.00	
22 FRONT FANFARE BRACKET - LH / RH X	2	\$	66.00	
23 FRONT FENDER - LH / RH X	2	\$	1,722.00	
24 FRONT FENDER ATTACHMENT PARTS X	2	\$	225.00	
25 FRONT FENDER CLOSING ELEMENT - LH / RH X	2	\$	162.00	
26 FRONT FENDER BRACKET - UPPER LH / RH X	2	\$	84.00	
27 POP RIVET X	12	\$	46.00	
28 FRONT FENDER BRACE - LH / RH X	2	\$	264.00	
29 FRONT WHEEL HOUSING LINER - LH / RH X	2	\$	522.00	
30 FRONT WHEEL SPOILER X	2	\$	164.00	
31 FRONT STONE CHIP GUARD X	2	\$	114.00	
32 FRONT FENDER LEDGE COVER X	2	\$	70.00	
33 BONNET LOCK ?	2	\$	455.00	
34 BONNET BOWDEN CABLE ?	1	\$	64.00	
35 BONNET RELEASE LEVER ?	1	\$	15.00	
36 BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00	
37 BONNET BOWDEN CABLE COVER ?	1	\$	11.00	
38 PLENUM CHAMBER COVER X	1	\$	108.00	
39 BONNET SOUND ABS / CRU	1	\$	382.00	
40 LED HEADLIGHT - LH / RH ?	2	\$	16,588.00	
SUB - TOTAL PARTS CHARGES	:	\$	21,265.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
 TEL : 6474 3323 FAX : 6264 6786
 EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 5813 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
				COST + 10 %
41 HEADLIGHT LIFT CLINDER - LH / RH ?	2	\$	462.00	
42 HEADLIGHT CORRUGATED PIPE ?	1	\$	107.00	
43 LOCK CARRIER ?	1	\$	1,478.00	
44 COOLANT REGULATOR COOLANT SUPPORT ?	2	\$	85.00	
45 A/C CONDENSER ?	1	\$	683.00	
46 A/C CONDENSER BRACKET ?	1	\$	21.00	
47 ADDITIONAL RADIATOR ?	1	\$	545.00	
48 RADIATOR ?	1	\$	699.00	
49 RADIATOR COOLANT 1.0 LTR ?	6	\$	297.00	
50 RADIATOR AIR GUIDE - LH / RH ?	2	\$	64.00	
51 RADIATOR AIR GUIDE - LH / RH INNER ?	2	\$	28.00	
52 RADIATOR AIR GUIDE - CENTRE ?	1	\$	19.00	
53 RADIATOR AIR GUIDE - LOWER ?	1	\$	25.00	
54 FRONT NO. PLATE ✓ BJ	S/N	\$	60.00	
55 SUNDRIES ?		\$	400.00	
TOTAL PARTS CHARGES	:	\$	33,042.00	
TOTAL LABOUR CHARGES	:	\$	4,500.00	
GRAND TOTAL	:	\$	37,542.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOCARE

24 BENOI SECTOR, SINGAPORE 629857
TEL : 6474 3323 FAX : 6264 6786
EMAIL: CLAIMS@PREMIUMAUTOCARE.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Steve (LKK)
:
: 5/11/12, 5:00pm
:
: OD-NWL
:
: EXCESS - ?
: PIP, My AIC 9.6 days

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6474 3323 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOCARE CENTRE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT