

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 24 Apr 2023

Preliminary Advice

Insured Vehicle No	: SLR3185T	Accident Date	: 30/09/2022
TP Vehicle No	: SNG6585L	Assignment Date	: 05/10/2022
Make	: SUBARU FORESTER	Est. Duration of Repair	: 6
Date of Inspection	: 10/10/2022		
Inspection At	: ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE, SINGAPORE 415933		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,552.60
Revised Amount	:S\$	6,596.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,596.96

Lump Sum Repair	:S\$	5,200.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.