



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
YIOW KOK PENG	Cust No/Name /YIOW KOK PENG
129 PASIR RIS GROVE	Reg No/Reg Date SMY7405J / 24/03/202
#06-07	Date In/Mileage / 0
SINGAPORE 518179	Chassis No KNAF5416MM5095937
Contact No Mobile: 97322285	Engine No G4FGKH739951
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	04/10/2022/ 19:14	TLE	261 / Edwin Caina	58324
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE FR DOOR PANEL & AFFECTED AREA				649 1920.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00
A 54900099	CHECK WIRING AND DOOR HANDLE FUNCTION				80.00
E PNT98000	SPRAY PAINT FRONT RIGHT DOOR PANEL, LOWER SKIRT, FRONT RIGHT PANEL				1100 1650.00
M MSUNDRY	SUNDRIES				20 50.00
M SUNDRY	SUPPLY BODY PNL SEALANT				40 80.00
E PNT88000	REMOVE & REFIT ALL RH/F DOOR COMPONENT				180 280.00
M PANEL ASSY-FRONT DOOR,RH	DD	1.00	1377.00	00.00	✓ 1377.00
M HANDLE ASSY-DOOR OUTSIDE,RH	X R	1.00	164.00	00.00	✓ 164.00
M MOULDING ASSY-FRT DR FRAME,RH	nc	1.00	72.00	00.00	✓ 72.00
M W/STRIP ASSY-FR DR BELT O/S RH	? X NN	1.00	80.00	00.00	✓ 80.00
M BLACK TAPE-FR DR RR,RH	nc	1.00	13.00	00.00	✓ 13.00

Estimate

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: 3/11/22, 3:39pm

DATE: 3/11/22

REMARKS: P/P

Confirm & accepted by

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on Net 6,046.00 423.22

Total Payable 6,469.22

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.