



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
YIOW KOK PENG 129 PASIR RIS GROVE #06-07 SINGAPORE 518179 Contact No Mobile: 97322285	Cust No/Name	/YIOW KOK PENG
	Reg No/Reg Date	SMY7405J / 24/03/202
	Date In/Mileage	/ 0
	Chassis No	KNAF5416MM5095937
	Engine No	G4FGKH739951
	Make/Model	KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	04/10/2022/ 19:14	TLE	261 / Edwin Caina	58324

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FR DOOR PANEL & AFFECTED AREA				1920.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				280.00
A 54900099 CHECK WIRING AND DOOR HANDLE FUNCTION				80.00
E PNT98000 SPRAY PAINT FRONT RIGHT DOOR PANEL, LOWER SKIRT, FRONT RIGHT PANEL				1650.00
M MSUNDRY SUNDRIES				50.00
M SUNDRY SUPPLY BODY PNL SEALANT				80.00
E PNT88000 REMOVE & REFIT ALL RH F DOOR COMPONENT				280.00
M PANEL ASSY-FRONT DOOR,RH	1.00	1377.00	00.00	1377.00
M HANDLE ASSY-DOOR OUTSIDE,RH	1.00	164.00	00.00	164.00
M MOULDING ASSY-FRT DR FRAME,RH	1.00	72.00	00.00	72.00
M W/STRIP ASSY-FR DR BELT O/S RH	1.00	80.00	00.00	80.00
M BLACK TAPE-FR DR RR,RH	1.00	13.00	00.00	13.00

SURVEYOR NAME : _____

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

Confirm & accepted by

7% GST on **6046.00** **423.22**

Nett 6,046.00

Total Payable 6,469.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.