

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : **Allianz Insurance Singapore Pte Ltd**
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : TP/102022/5695
Date : 06-10-2022
Accident Date : 03-10-2022

Vehicle Details

Make & Model : Mercedes Benz E250 SEDAN
EDITION E (R18 LED SR)
Chassis No : WDD2120362B241808
Registration No : SMH9088S

Third Party Vehicle Details

Registration No : SML4922X

S/N	Description	Qty	Amount (\$S)
1	REAR BUMPER <i>ll</i>	1.00	\$1,350.00 <i>1100 ✓</i>
2	REAR BUMPER CENTER PAD <i>ll</i>	1.00	\$200.00 <i>✓</i>
3	REAR BUMPER CENTER CHROME MOULDING <i>2 Cut</i>	1.00	\$180.00 <i>✓</i>
4	REAR BUMPER PARKING SENSOR <i>2 Cut</i>	2.00	\$220.00 <i>✓</i>
5	REAR BUMPER RH SIDE RETAINER <i>2 3/4 nn</i>	1.00	\$30.00 <i>×</i>
6	REAR BUMPER LH SIDE RETAINER <i>2 3/4 nn</i>	1.00	\$30.00 <i>×</i>
7	REAR BUMPER REINFORCEMENT <i>2 BT BR</i>	1.00	\$700.00 <i>500 ✓</i>
8	REAR BUMPER INNER BRACKET <i>2 nn</i>	1.00	\$160.00 <i>✓</i>
9	REAR KEYLESS SENSOR <i>2 nn</i>	1.00	\$380.00 <i>×</i>
10	REAR KEYLESS SENSOR WIRE A <i>X 3/4 nn</i>	1.00	\$90.00 <i>×</i>
11	REAR KEYLESS SENSOR WIRE B <i>X 3/4 nn</i>	1.00	\$90.00 <i>×</i>
12	REAR KEYLESS SENSOR WIRE HOLDER <i>2 nn</i>	1.00	\$40.00 <i>×</i>
			2360
			+10%
			2596
			\$3,470.00
			Margin: 10%
			\$347.00
			\$3,817.00 <i>400</i>

13 TO REPAIR DAMAGES 1.00 \$580.00 *200*

14 TO SPRAY PAINTING 1.00 \$680.00 *200*

1000

Subtotal w/o GST:

\$5,077.00 *600*

3596

4 Days.
P/P before paint, etc.
600
12/10.

Issued by Iswan

This is a computer-generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damage 1 part(s) during resurvey
- Parts prices are subject to configuration
- Third party survey on "Without Prejudice" basis
- No illegal modification allowed
- Supplemental survey may be surveyed and is subject to approval by the Insurance Company

Acknowledged by Repairer: 1 of 1
Signature:
Date: