

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

ALLIANZ INSURANCE SINGAPORE PTE LTD
 79 Robinson Road #09-01
 Singapore 068897

Xiao Tony

Quotation
 DATE : 10.10.2022
 VEH NO : SFZ8838P
 MODEL : Mazda 3
 D O A : 24.09.2022
 YR REF : EY10E

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SFZ8838P (MAZDA 3)

| <u>Item</u> | <u>Description</u> | <u>Qty</u> | <u>Amt</u> |
|--------------------------|--|------------|-------------------|
| <u>LIST ITEMS</u> | | | |
| 1 | Rear Bumper <i>Dehd</i> | 1 | 997.40 ✓ |
| 2 | Rear Bumper Side Holder - RH <i>R.d.</i> | 1 | 68.40 ✓ |
| 3 | Rear Bumper Reflector - RH <i>Ne see</i> | 1 | 87.20 x |
| 4 | Rear Bumper Side Undercover - RH <i>Dehd</i> | 1 | 75.40 ✓ |
| 5 | Rear Fender - RH <i>Distorted</i> | 1 | 1,643.60 ✓ |
| 6 | Rear Fender Inner Trim Board - RH <i>new</i> | 1 | 4020.40 641.90 x. |
| 7 | Rear Fender Inner Shield - RH <i>Dehd</i> | 1 | 3216.32 182.40 ✓ |
| 8 | Rear Fender Air Vent - RH <i>Ne m</i> | 1 | 43.10 x. |
| 9 | Taillamp - RH <i>cut</i> | 1 | 903.30 ✓ |
| 10 | Rear Windscreen Moulding <i>m</i> | 1 | 149.90 ✓ |
| | | | 4,792.60 |
| Less 20% | | | (958.52) |
| | | | 3,834.08 |

S/NETT ITEMS

| | | | |
|-------------|---|-------|------------------|
| 1 | Rear Bumper Clips <i>Ne</i> | 1 set | 30.00 ✓ |
| 2 | Rear Fender Inner Trim Board Clips - RH <i>Ne m</i> | 1 set | 30.00 x |
| 3 | Rear Fender Inner Shield Clips - RH <i>Ne</i> | 1 set | 30.00 ✓ |
| 4 | Rear Wheel Rim - RH <i>cut</i> | 1 | 800 1,000.00 680 |
| 5 | Rear Tyre - RH <i>new</i> ✓ CUT | 1 | 300.00 ✓ 220 |
| 6 | Rear Windscreen Sealant <i>per</i> | 1 | 60.00 ✓ |
| Total Parts | | | \$ 5,284.08 |

LABOUR CHARGE

| | | | |
|---|---|----|--------------|
| 1 | To knocking & pull out rear portion & renew parts | \$ | 1,200.00 700 |
|---|---|----|--------------|

RE : ESTIMATE FOR ACCIDENT REPAIR SFZ8838P (MAZDA 3)

| | | | | |
|--------------|---------------------------------|----|----------|-----|
| 2 | To putty & spray up paint works | \$ | 1,000.00 | 700 |
| 3 | To check wiring | \$ | 50.00 | 30 |
| 4 | To spray tuff coat | \$ | 150.00 | 60 |
| 5 | To remove upholstery | \$ | 150.00 | 60 |
| 6 | To remove rear windscreen | \$ | 180.00 | 120 |
| 7 | To remove reverse sensor | \$ | 100.00 | 50 |
| 8 | To perform wheel alignment | \$ | 150.00 | 80 |
| Total Labour | | \$ | 2,980.00 | |
| Grand Total | | \$ | 8,264.08 | |

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

6,036.32
~~total: 5816.32~~
~~l/s: 4650~~
 4,800.00
 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

