

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail: sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP Allianz
Xiao Tony

CAPITAL CAR LEASING PTE LTD
171 CHIN SWEE ROAD #04-08/09 CES
CENTRE
SINGAPORE 169877

TAX INVOICE

Repair Code : CLM17401

Date in : 02/10/2022

Vehicle Num. : SNG4915G

Model : TOYOTA SIENTA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707271516/1NZ9410115

Contact : 87420435, 93634351

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR <i>Dented.</i>	1	1184.50	✓ 1,184.50
FRONT LH DOOR GLASS REGULATOR <i>Xse New</i>	1	381.40	X 381.40
FRONT LH DOOR INNER PLASTIC SEAL COVER <i>Xse New</i>	1	41.80	X 41.80
FRONT LH DOOR UPPER MOULDING RIVET <i>Xse New</i>	8	2.50	X 20.00
FRONT LH DOOR VERTICAL GARNISH <i>New</i>	1	62.15	✓ 62.15
FRONT LH DOOR WEATHER STRIP <i>ut</i>	1	255.20	✓ 255.20
LH CENTER PILLAR <i>Dented.</i>	1	464.20	✓ 464.20
LH SLIDING DOOR <i>Dented.</i>	1	1294.90	✓ 1,294.90
LH SLIDING DOOR GLASS REGULATOR <i>Xse New</i>	1	253.90	X 253.90
LH SLIDING DOOR GLASS REGULATOR MOTOR <i>Xse New</i>	1	704.80	X 704.80
LH SLIDING DOOR INNER PLASTIC SEAL COVER <i>Xse New</i>	1	35.20	X 35.20
LH SLIDING DOOR INNER TRIM BOARD <i>crack d.</i>	1	1017.00	779. 1017.00
LH SLIDING DOOR LOWER ROLLER BRACKET <i>Xse New</i>	1	293.80	X 293.80
LH SLIDING DOOR LOWER ROLLER SLIDE LOCK <i>Xse New</i>	1	61.90	X 61.90
LH SLIDING DOOR MECHANISM LOCK <i>Xse New</i>	1	571.00	X 571.00
LH SLIDING DOOR PROTECTOR GARNISH <i>Xse New</i>	1	111.80	X 111.80
LH SLIDING DOOR SIDE SENSOR MOULDING <i>torn</i>	1	1292.20	1065 1292.20
LH SLIDING DOOR VERTICAL GARNISH (FRONT) <i>New</i>	1	62.15	✓ 62.15

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
171 CHIN SWEE ROAD #04-08/09 CES
CENTRE
SINGAPORE 169877

Contact : 87420435, 93634351

TAX INVOICE

Repair Code : CLM17401

Date in : 02/10/2022

Vehicle Num. : SNG4915G

Model : TOYOTA SIENNA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707271516/1NZ9410115

LH SLIDING DOOR VERTICAL GARNISH (REAR) <i>Nec</i>	1	111.80	✓ 111.80
Subtotal before discount			8,219.70
Percentage discount 25%			2,054.93
Sub-total 1			6,164.78
DOOR VISOR GARNISH - SET <i>New</i>	1	250.00	150. ✓ 250.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET <i>Nec</i>	1	50.00	✓ 50.00
LH SLIDING DOOR INNER TRIM BOARD CLIPS - SET <i>Nec</i>	1	50.00	30. ✓ 50.00
Subtotal before discount			350.00
Percentage discount 0%			0.00
Sub-total 2			350.00
Parts-total			6,514.78

LABOUR

To reset system after repair works

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

✓ 250.00

60. ✓ 150.00

160. ✓ 200.00

800. ✓ 1,200.00

900. ✓ 1,400.00

60. ✓ 120.00

3,320.00

9,834.78

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 2

4.9K

total 6819.17

2/5: 4.9K.

08 Days.