

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22009861/KPA3Q2**Date:** 20/06/2023**REFERENCE**

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | Allianz Insurance Singapore Pte. Ltd. | Policy No:                  | SP2002495301-01 |
| <b>Claimant Vehicle No :</b> | GBG5033L                              | <b>Insured Vehicle No :</b> | SLG1485Z        |
| Date of Loss:                | 30/09/2022                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | 202222007179    |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBG5033L</b>                   |             |                   |
| Make & Model:               | TOYOTA HIACE, 3.0 D TURBO 4DR (A) | Engine No:  | 1KD2703915        |
| Reg. Date:                  | 22/08/2017 (Man. Year: 2017)      | Chassis No: | JTFHT02P300221166 |
| Colour:                     | Silver                            | Odometer:   | 135892 km         |
| Engine Capacity:            | 2982 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195 R15X8        | Rear Tyre Size:  | 195 R15X8        |
| Front Left Side:  | Bridgestone 8 mm | Rear Left Side:  | Bridgestone 2 mm |
| Front Right Side: | Bridgestone 8 mm | Rear Right Side: | Bridgestone 2 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 2,773.40          | 2,160.70          | 612.70            | 22.09         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 3,300.00          | 2,700.00          | 600.00            | 18.18         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>6,073.40</b>   | <b>4,860.70</b>   | <b>1,212.70</b>   | <b>19.97</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>3,700.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 6,073.40          | 3,700.00          | 2,373.40          | 39.08         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 425.14            | 259.00            | 166.14            | 39.08         |
| <b>Nett Amount (S\$)</b>                        | <b>6,498.54</b>   | <b>3,959.00</b>   | <b>2,539.54</b>   | <b>39.08</b>  |
| <b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b> |                   | 700.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>4,661.00</b>   |                   |               |

**INSPECTION**

|                             |            |                                                                                                                      |
|-----------------------------|------------|----------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 05/10/2022 |                                                                                                                      |
| Date Inspected:             | 12/10/2022 | Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)<br>Blk 1019 #01-374/382, Yishun Industrial Park A<br>Singapore 768761 |
| Estimated Period of Repair: | 6.0 days   |                                                                                                                      |

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                    |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                    |
| Part Source:  | (Last Synchronised: 19 Jun 2023)                                                                                                                                             |                                                                    |
| Parts:        | N/A                                                                                                                                                                          | TOYOTA HIACE 3.0 D TURBO 4DR (A) (Model not available in database) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| Print Code:   | (Unsubmitted, no print-code for GBG5033L)                                                                                                                                    |                                                                    |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

Recommended Parts

| No. | Qty | Part No. | Particulars                       | Condition              | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------|------------------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                      | Bent                   | 150.00 F   | *150.00 FL |
| 2   | 1   |          | *REAR BUMPER LH RETAINER          | Distorted              | 18.00 F    | *18.00 FL  |
| 3   | 6   |          | *REAR BUMPER CLIPS                | Missing                | 12.00 F    | *12.00 FL  |
| 4   | 1   |          | *LH TAILLAMP                      | Chipped                | 105.00 F   | *105.00 FL |
| 5   | 1   |          | *LH TAILLAMP LOWER FILLER PANEL   | Buckled                | 45.00 F    | *45.00 FL  |
| 6   | 1   |          | *REAR TAILGATE                    | Bent                   | 750.00 F   | *750.00 FL |
| 7   | 1   |          | *TAILGATE OUTER GARNISH           | Serviceable            | 65.00 F    | *- FL      |
| 8   | 1   |          | *TAILGATE CENTRE LOGO             | Necessary              | 28.00 F    | *28.00 FL  |
| 9   | 1   |          | *TAILGATE STICKER -TOYOTA HIACE   | Necessary              | 25.00 F    | *25.00 FL  |
| 10  | 1   |          | *TAILGATE INNER LOCK              | Jammed                 | 95.00 F    | *95.00 FL  |
| 11  | 1   |          | *TAILGATE LOCK STRIKER            | Repair                 | 38.00 F    | *- FL      |
| 12  | 10  |          | *TAILGATE INNER TRIM BOARD CLIPS  | Necessary              | 20.00 F    | *20.00 FL  |
| 13  | 1   |          | *TAILGATE WEATHERSTRIP            | Buckled                | 135.00 F   | *135.00 FL |
| 14  | 1   |          | *REAR END PANEL OUTER             | Bent                   | 130.00 F   | *130.00 FL |
| 15  | 1   |          | *REAR END PANEL INNER             | Bent                   | 380.00 F   | *380.00 FL |
| 16  | 1   |          | *REAR END PANEL TOP GARNISH PLATE | Distorted              | 50.00 F    | *50.00 FL  |
| 17  | 4   |          | *REAR END PANEL LOWER BRACKETS    | Distorted (2 PCS ONLY) | 60.00 F    | *30.00 FL  |
| 18  | 1   |          | *SPARE TYRE CARRIER               | Distorted              | 150.00 F   | *150.00 FL |
| 19  | 1   |          | *SPARE TYRE CARRIER HOOK          | Repair                 | 20.00 F    | *- FL      |
| 20  | 1   |          | *SPARE TYRE CARRIER BOLT          | Repair                 | 18.00 F    | *- FL      |
| 21  | 1   |          | *SET REVERSE SENSOR               | Dented                 | 200.00 FS  | *200.00 FS |
| 22  | 1   |          | *REAR WINDSCREEN GLASS GUM        | Necessary              | 40.00 FS   | *40.00 FS  |
| 23  | 1   |          | *STICKER -70KM/H                  | Necessary              | 10.00 FS   | *10.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                    |          |          |
|----------------------------------------------------|----------|----------|
| Sub Total (\$\$)                                   | 2,544.00 | 2,373.00 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00     | 212.30   |
| + Margin on L,N Items 10.00/0.00% (\$\$)           | 229.40   | 0.00     |
| Total Parts (\$\$)                                 | 2,773.40 | 2,160.70 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                                                               | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                                                                                           |          |                 |                 |
| 1                              | REMOVE DAMAGED BUMPER ,TAILGATE ,REPAIR REAR FLOOR PANEL ,LH SIDE BODY PANEL ,LH INNER SIDE PANEL ,CUT ,WELD & REPLACE DAMAGED BODY PARTS | New      | 1,300.00        | 1,000.00        |
| 2                              | REMOVE AND REFIX REAR WINDSCREEN GLASS                                                                                                    | New      | 100.00          | 100.00          |
| 3                              | REMOVE & REFIX REVERSE CAMERA, REVERSE SENSOR                                                                                             | New      | 60.00           | 60.00           |
| 4                              | PUTTY & RESPRAY PAINT ON REAR BUMPER ,TAILGATE ,LH & RH SIDE PANELS ,REAR END PANEL FLOOR PANEL                                           | New      | 1,150.00        | 1,000.00        |
| 5                              | RUSTPROOFING                                                                                                                              | New      | 80.00           | 60.00           |
| 6                              | TO REWRITE ADVERTISEMENT                                                                                                                  | New      | 260.00          | 200.00          |
| 7                              | R&R REAR WOODEN BOARD AND ETC                                                                                                             | New      | 350.00          | 280.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                                                           |          | <b>3,300.00</b> | <b>2,700.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >