



UCB Engineering Pte Ltd

Business Reg. No. 199501338G

Our ref: 221001.TM(PC6651B)

05 October 2022

Travel Ministry Pte Ltd
Blk 535 Bukit Panjang Ring Road
#19-819
Singapore 670535

QUOTATION
without Prejudice

Dear Sir,

COST OF REPAIR FOR PC 6651 B

<u>QTY</u>	<u>DESCRIPTIONS</u>	<u>PRICE</u> S\$
1 pc	Rear view electric mirror – LHS / BR	1,600.00
	Labour charges for remove & replace the damaged parts And checking alignment	300.00 200
	To putty & spray painting onto rear view mirror	300.00 150
	Wiring charges	30.00 /
	TOTAL	2,230.00 =====

(SGD: Two Thousand Two Hundred And Thirty Only)

Yours faithfully,
Tan Tiong Chia

Sten (LKK)
6/10/22, 10.00 AM
w/ R
P/P
Lg BR Lg
2 djs

2C Jalan Pesawat, Jurong, Singapore 619359

Tel : 6268 1281

E-mail : unitedcb@singnet.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: