

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 09 Nov 2022

## **Preliminary Advice**

Insured : GBL918R

Vehicle No

TP Vehicle : SMH6655A  
No

Accident Date : 04/10/2022

Make : MERCEDES-BENZ C180

Assignment Date : 06/10/2022

Date of : 25/10/2022

Est. Duration of : 4  
Repair

Inspection

Inspection At : CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP)  
188 PANDAN LOOP  
SINGAPORE 128378

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 14,503.27

Revised Amount :S\$ 10,203.47

Check Items (Estimated) :S\$ 0.00

Total :S\$ 10,203.47

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$

COE / PARF Rebate :S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.