



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SMH6655A*RA

ECICS Limited

Motor Claims Department
10 Eunus Road 8
#09-04A Singapore Post Centre
Singapore 408600
63374779

Vehicle & Document Information
WIP No 60053
Reg No/Reg Date SMH6655A*RA / 08/01/2015
Date In/Mileage 01/09/2022
Chassis No WDD2050402R010104
Engine No 27491030222049
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 755 Tenorite Gr/ 041 115 Pebble

Account No	Terms	Date/Time Printed	CSE	Operator				
WE000073	Credit	05/10/2022/ 11:48	K0	301 / Kerlyn Ong				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : 2070099262-02 // 04/10/2022
DRIVE IN/TP VEHICLE NO. : 05/10/2022 // GBL918R - ECICS
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER & RH/ FRONT FENDER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT

M FRONT BUMPER

M RH/ FRONT BUMPER LOWER GRILLE

M RH/ FRONT BUMPER TOP BOTTOM MOLDING

M RH/ FRONT BUMPER BOTTOM MOLDING

M RH/ FRONT BUMPER MOUNTING RAIL

M RH/ BASIC MOUNTING FOR BUMPER

M FRONT DISTANCE SENSOR

M RH/ FRONT FENDER

M RH/ FRONT WHEEL HOUSE FRT COVERING

M RH/ HEADLAMP UNIT

M RH/ HEADLAMP UNIT CONTROL UNIT

M FRONT STIFFENING

1.00	1674.18	00.00	1674.18 ✓
1.00	89.47	00.00	89.47
1.00	62.67	00.00	62.67
1.00	85.57	00.00	85.57
1.00	15.52	00.00	15.52
1.00	99.71	00.00	99.71
1.00	195.43	00.00	195.43
1.00	977.57	00.00	977.57 ✓
1.00	134.11	00.00	134.11
1.00	3443.48	00.00	3443.48 ✓
1.00	645.87	00.00	645.87
1.00	851.45	00.00	851.45

Steve (LKK)
25/10/22, 12:30

Confirmed & accepted by

4 dys
PIP
BL y

Kerlyn Ong Kal Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Authorized signatory and company stamp

Nett	14,415.03
7% GST on	14415.03
Total Payable	15,424.08

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repairs have commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Acknowledged by Repairer

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 1