

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III22002947/TCY3E2-1**Date:** 17/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : FBQ8454H **Insured Vehicle No :** GBL2335J

Date of Loss: 06/01/2022 Nature of Claim: TP Claim No: MFL2022D0000256

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ8454H**

Make & Model: HONDA CB150R, 149cc Engine No: KC32E0040162

Reg. Date: 23/12/2019 (Man. Year: 2019) Chassis No: MLHKC288XK5140162

Colour: Multi-colour Odometer: 0 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 150/60 R17 Rear Tyre Size: 150/60 R17

Front Left Side: Metzeler 5 mm Rear Left Side: Metzeler 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,692.57	2,644.60	2,047.97	43.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	890.00	730.00	45.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,312.57	3,534.60	2,777.97	44.01
Approved Total (Overridden) (S\$)		2,800.00		
Nett Amount (S\$)	6,312.57	2,800.00	3,512.57	55.64

INSPECTION

Date of Assignment: 05/10/2022

Date Inspected: 31/03/2022 Inspected At: BIKES & TEA PTE L (HQ)
25 Kaki Bukit Road 4, #01-28, Synergy @ KB,
Singapore 417800

Estimated Period of Repair: 5.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Oct 2022)	
Parts:	N/A	HONDA CB150R 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ8454H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	120.50 FL	*120.50 FL
2	1		*SET HANDLE GRIP	Torn	60.00 FL	*60.00 FL
3	1		*SET HANDLE BAR END	Cut	80.00 FL	*80.00 FL
4	1		*BRAKE LEVER	Bent	24.80 FL	*24.80 FL
5	1		*CLUTCH LEVER	Cut / Bent	40.60 FL	*40.60 FL
6	1		*SET MIRROR	Cut	120.00 FL	*120.00 FL
7	1		*FRONT SIGNAL LIGHT LH (LED)	Grazed	92.80 FL	*92.80 FL
8	2		*FRONT FORK ASSY	Not Necessary	1,160.00 FL	*- FL
9	1		*FUEL TANK SIDE COWLING	N/S Hdr Cracked	235.80 FL	*117.90 FL
10	1		*FRONT SHROUD COMPLETE LH	Grazed / Cut	105.00 FL	*105.00 FL
11	1		*FRONT SHROUD INNER LH	Not Necessary	75.50 FL	*- FL
12	1		*FRONT FOOTREST LH	Broken	64.35 FL	*64.35 FL
13	1		*FRONT FOOTREST BRACKET LH	Bent	109.50 FL	*109.50 FL
14	1		*GEAR SHIFT PEDAL	Bent / Cut	98.00 FL	*98.00 FL
15	1		*BRAKE PEDAL	Bent	68.00 FL	*68.00 FL
16	1		*REAR BRAKE CALIPER	Cut / Grazed	325.00 FL	*325.00 FL
17	1		*REAR BRAKE DISC	Warped	285.00 FL	*285.00 FL
18	2		*REAR PILLION FOOTREST	Bent / Cut	77.00 FL	*77.00 FL
19	1		*REAR SWING ARM ASSY	Distorted	549.90 FL	*450.00 FL
20	1		*SET STEERING CONE & BEARING	Not Necessary	210.00 FS	*- FS
21	1		*SET REAR SWING ARM BUSHES	Necessary	160.00 FS	*80.00 FS
22	1		*SET REAR BOX RACK WITH BASE	Not Necessary	250.00 FS	*- FS
23	1		*REAR ALUMINIUM BOX	Cut / Dented	750.00 FS	*550.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,061.75	2,868.45
- List Item Discount on L Items 10.00/10.00% (\$\$)	369.18	223.85
Total Parts (\$\$)	4,692.57	2,644.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORTATION (2 TRIPS)	New	150.00	120.00
2	FRONT FENDER RESPRAY	New	100.00	60.00
3	STEERING STEM REPAIR & ALIGN	New	200.00	120.00
4	BODY CHASSIS REPAIR & ALIGNMENT	New	550.00	150.00
5	REAR WHEEL RIM BALANCE	New	120.00	40.00
6	LABOUR TO RENEW DAMAGED PARTS	New	500.00	400.00
Gross Labour Cost (S\$)			1,620.00	890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >