



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM22009875/Rcy3e2 Date: 03/11/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3064E	Veh. Inspected	SBS 3154X
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04C61	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	05/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO B9TL	c.c	9364
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	YV3S4P924CA156438	Colour	MULTI COLOUR
	Odometer	825227 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/10/2022	Inspection Date	05/10/2022
	Survey held at	ANG MO KIO DEPOT - 15 Ang Mo Kio St 63		
	Repairer	SBS TRANSIT LTD (HQ)		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	