



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PANEL

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b> REPLACEMENT OF 3 PANEL OF SOUTH ELEVATION. A)MATERIAL SUPPLY OF 3PCS OF 100MM TRIMO PANEL IN RAL 9006. SUPPLY OF NEW FLASHING MATERIAL. B)INSTALLATION REMOVAL AND DISPOSAL OF EXISTING 3 PANELS. INSTALL OF NEW PANELS. NECESSARY FLASHING WORK. PRELIMINARIES MOBILIZATION MEWP. SCISSOR LIFT ARRANGEMENT. DISCOUNT		9,000.00	9,000.00
			2,400.00	2,400.00
			-600.00	-600.00
			10,800.00	10,800.00
	<b>GRAND TOTAL</b>		<b>10,800.00</b>	<b>10,800.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>9,720.00</b>

Report Ref No. CS1/LPM22009877/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.