



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE		Ref: CC4/ASM22009880/Gpa3q2 Date: 16/06/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 6221P	Veh. Inspected	SNL 6005K
Policy No.	P2465679	Coverage (\$)	0.00
Claim No.	S2M04C9D	Excess (\$)	0.00
Assign From		Assign Date	06/10/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HONDA FIT BASIC 1.3	c.c	1317
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	GR11108655	Colour	WHITE
Odometer	53471 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/60 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/60 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/60 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/60 R15	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	04/10/2022	Inspection Date	06/10/2022
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	