



Pte Ltd

TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
REPAIR PERFORMA INVOICE

bizSAFE
 S T A R



Vehicle number	SND6005K
Make / Model	HONDA FIT
Chassis number	GR11108655
Accident date	4/10/22
Reference	2210-01

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER / Re	781.00
2	REAR BUMPER RETAINER X	55.00
1	REAR BUMPER REFLECTOR RH X	58.30
1	REAR BUMPER SPONGE X NN	79.50
1	TAILGATE / Re	1138.50
1	TAILGATE LOCK X	187.00
1	TAILGATE LOCK STRIKER X	36.00
1	TAILGATE RUBBER X	102.50
1	TAILGATE EMBLEM - LOGO X	44.85
1	TAILGATE EMBLEM - FIT / Re	44.85
1	TAILGATE WINDSCREEN MOULDING / Re	126.50
1	TAILGATE INNER TRIM BOARD X NN	218.00
1	END PANEL ?	506.00
1	END PANEL TOP GARNISH X	105.00
2	TAILLAMP X	780.00
2	TAILLAMP LOWER BRACKET X	145.00
1	REAR FENDER INNER TRIM BOARD RH X	308.00
		4716.00
	Less 20%	943.20
	Subtotal	3772.80
	Balance C/F	3772.80
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP / Re	50.00
1 SET	REVERSE SENSOR X NN	250.00
1 SET	TAILGATE INNER TRIM BOARD CLIP / Re	50.00
1	TAILGATE WINDSCREEN SEALANT / Re	120.00
	Subtotal	470.00
	Balance C/F	4242.80
LABOUR AND MISCELLANEOUS CHARGES		
1	CHECK WIRING AND LIGHTINGS SYSTEM	120.00 X NN
2	REMOVE TRIMS & GARNISHES TO FACILITATE REPAIR	200.00 60
3	REMOVE & REFIT TAILGATE GLASS	200.00 120
4	REMOVE & REPLACE REVERSE SENSOR	150.00 40
5	PANEL BEATING ON AFFECTED AREAS	1000.00 400
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 400
7	APPLY ANTI RUST ON AFFECTED AREAS	200.00 X NN
	Subtotal	2870.00

Grand total

7112.80

4 Days.

4/5

After repair photos

Erica Qiang

6/10/22

LKK Auto Consultants hence notify
the Repairer of the following:

- before/after spray painting
- (s) during resurvey
- information
- a "Prejudice" basis
- be surveyed and
- Insurance Company

Signature: _____

Date: _____