

TSL Auto Garage
 Blk 4 Joo Chiat Complex
 #12-1171 Joo Chiat Road
 Singapore 420004

KDY 231

JTFAT35

GBA820X Toyota Dyna

No	Qty	Parts Description	Estimated Parts Price
1	1	Front left door side step garnish	\$ 267.00 X
2	1	Front left knuckle arm	\$ 787.00 ^
3	1	Front left wheel hub with bearing	\$ 306.00 X NN
4	1	Front left shock absorber	\$ 379.00 X
5	1	Front left lower arm	\$ 489.00 X
6	1	Front left upper arm	\$ 519.00 X
7	1	Front left mudguard	\$ 392.00 ²⁹⁰ 190
8	1	Front left fuel filter	\$ 280.00 175
9	1	Front left inner cowling	\$ 185.00 X nn
10	1	Front battery bracket	\$ 220.00 bt -
11	1	Fron left tailgate lower side panel	\$ 1,654.00 bt - 500 700
12	1	Front left cabin opening handle with lock mechansim	\$ 953.00 bt - 531 581
13	1	Front intake resonator assy	\$ 454.00 X nn
14	1	Rear left tailgate assy	\$ 1,850.00 bt - 1645
15	3/8	Rear left tailgate hinges @64.40	\$ 350.00 bt - X 193.20
16	1	Rear left tailgate top lock	\$ 248.00 X nn
17	2	Rear left tailgate rubber stopper	\$ 28.00 mis -
18	1	Rear left tailgate rubber stopper bracket	\$ 56.00 bt -
19	1 set	Rear left mudguard	\$ 385.00 bt - 225
			\$ 9,802.00
Less 25%			\$ 2,450.50
			\$ 7,351.50
<u>Special Nett Items</u>			
1	1	Rear left top railing	\$ 1,600.00 X nn
2	1	Front left door company sticker	\$ 50.00 X
3	1	Front left battery	\$ 250.00 180
4	1	Front left tyre	\$ 300.00 X
5	1	Rear left tyre	\$ 300.00 X nn
6	1	Rear left wheel rim	\$ 450.00 300
7	1	Front left wheel rim	\$ 650.00 X
8	1	Front no plate	\$ 80.00 X nn
			\$ 3,680.00
Total parts			\$ 11,031.50

TSL Auto Garage
 Blk 4 Joo Chiat Complex
 #12-1171 Joo Chiat Road
 Singapore 420004 .

GBA820X Toyota Dyna

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,600.00 700
2	To putty and spray painting accident portion.	\$ 1,600.00 800
3	To remove and install front left undercarriage parts.	\$ 350.00 X
4	To apply anti rust proofing to accident affected area.	\$ 140.00 50
5	To balance rear left wheel.	\$ 50.00 30
6	To balance front left wheel.	\$ 50.00 X
7	To conduct wheel alignment.	\$ 150.00 80
8	Towing service.	\$ 100.00 ?X
Total labour :		\$ 4,040.00

Total parts : \$ 11,031.50
Total labour : \$ 4,040.00
Total repair cost : \$ 15,071.50

Tanji 97495749
 WP 6/10/22 e
 L/S Resurvey after repair
 temp file @ Whantown
 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

GBA820X Toyota Dyna

No	Qty	Parts Description	Estimated Parts Price
1	1	Front left door side step garnish	\$ 267.00 x
2	1	Front left knuckle arm	\$ 787.00 ^
3	1	Front left wheel hub with bearing	\$ 306.00 x
4	1	Front left shock absorber	\$ 379.00 x
5	1	Front left lower arm	\$ 489.00 x
6	1	Front left upper arm	\$ 519.00 x
7	1	Front left mudguard	\$ 392.00 de -
8	1	Front left fuel filter	\$ 280.00 dol -
9	1	Front left inner cowling	\$ 185.00 x
10	1	Front battery bracket	\$ 220.00 bt -
11	1	Fron left tailgate lower side panel	\$ 1,654.00 bt -
12	1	Front left cabin opening handle with lock mechansim	\$ 953.00 bt -
13	1	Front intake resonator assy	\$ 454.00 x
14	1	Rear left tailgate assy	\$ 1,850.00 bt -
15	3/6	Rear left tailgate hinges	\$ 350.00 bt -
16	1	Rear left tailgate top lock	\$ 248.00 x
17	2	Rear left tailgate rubber stopper	\$ 28.00 mis -
18	1	Rear left tailgate rubber stopper bracket	\$ 56.00 bt -
19	1 set	Rear left mudguard	\$ 385.00 bt -
			\$ 9,802.00
		Less 25%	\$ 2,450.50
			<u>\$ 7,351.50</u>
		<u>Special Nett Items</u>	
1	1	Rear left top railing	\$ 1,600.00 x
2	1	Front left door company sticker	\$ 50.00 x
3	1	Front left battery	\$ 250.00 de ✓
4	1	Front left tyre	\$ 300.00 x
5	1	Rear left tyre	\$ 300.00 x
6	1	Rear left wheel rim	\$ 450.00 dol -
7	1	Front left wheel rim	\$ 650.00 x
8	1	Front no plate	\$ 80.00 x
			<u>\$ 3,680.00</u>
		Total parts	\$ 11,031.50

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

GBA820X Toyota Dyna

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,600.00 700
2	To putty and spray painting accident portion.	\$ 1,600.00 800
3	To remove and install front left undercarriage parts.	\$ 350.00 x
4	To apply anti rust proofing to accident affected area.	\$ 140.00 50
5	To balance rear left wheel.	\$ 50.00 30
6	To balance front left wheel.	\$ 50.00 x
7	To conduct wheel alignment.	\$ 150.00 80
8	Towing service.	\$ 100.00 ?
Total labour :		\$ 4,040.00

Total parts : \$ 11,031.50
Total labour : \$ 4,040.00
Total repair cost : \$ 15,071.50

Taufik 97495749
 WP: 0/10/27 E
 LS Repair at the repair
 Taufik @ (Kuantan)
 06 days