



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: HO WINNIE		Ref: CS/ASM22009881/Tvy3e2 Date: 16/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8534H	Veh. Inspected	GBA 820X
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S2M04BWK	Excess (\$)	0.00
Assign From	HO WINNIE	Assign Date	05/10/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JTFAT35Y903000371	Colour	SILVER
Odometer	594510 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/75 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	155 R12	DUNLOP	6 mm
L/H Rear Tyre	155 R12	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/09/2022	Inspection Date	06/10/2022
Survey held at	TSL AUTO GARAGE BLK 1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	