

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 25 Oct 2022

**Preliminary Advice**

Vehicle No	: SBA71R	Accident Date	: 28/09/2022
Make	: HYUNDAI ELANTRA	Policy No.	: SP2002389349
Assignment Date	: 06/10/2022	Excess	: S\$2,000.00
Date of Inspection	: 06/10/2022	Est. Duration of Repair	: 5
Inspection At	: KAN FOOK SING MOTOR WORKSHOP		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,919.50 (incl.supplementary \$1124.50)
Revised Amount	:S\$	3,657.50
Check Items (Estimated)	:S\$	899.80
Total	:S\$	4,557.30
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	30,279.00
Salvage Value	:S\$	
Margin for Repair	:S\$	35,721.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.