



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Reg.No.: 52888887X

QUOTATION

No : QT-000310

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

TEL : 63953836

FAX :

Your Ref. : SNE5651X
Vehicle No. : SLK9938K
Make & Model : TOYOTA HARRIER
Chassis No. : ZSU600081943
Engine No. : 3ZRB812314
Accident Date : 03-10-2022
Policy No. : 5086814981-05
Date : 04-10-2022
Page : 1 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
1	REAR BUMPER <i>20/02</i>	1.0	1,395.30	1,395.30
2	REAR BUMPER LIP <i>3 days</i>	1.0	401.95	401.95
3	REAR BUMPER REFLECTOR (L/H) <i>6/10/22</i>	1.0	62.60	62.60
4	REAR BUMPER SPONGE <i>L/S #1600</i>	1.0	106.40	106.40
5	BUMPER CLIP <i>turn</i>	8.0	4.20	33.60
6	REAR END PANEL <i>11</i>	1.0	786.90	786.90
7	CONTROL UNIT (CENTRAL DOOR LOCK) <i>11</i>	1.0	572.50	572.50
8	REAR BUMPER SIDE RETAINER (LAMP) <i>11</i>	2.0	104.30	208.60
9	BUMPER SIDE RETAINER (L/H/R) <i>Benf</i>	1.0	71.50	71.50
10	BUMPER SIDE RETAINER (R/H/R) <i>11</i>	1.0	71.50	71.50
11	EMBLEM "HARRIER" <i>11</i>	1.0	63.60	63.60
12	REAR BOOT <i>11</i>	1.0	1,232.70	1,232.70
13	WINDSCREEN MOULDING (REAR) <i>11</i>	1.0	89.90	89.90
14	Discount 25 %			-1,274.26
15	SubTotal (L)			3,822.79
16	REAR END PANEL SEALANT <i>11</i>	1.0	50.00	50.00
17	SEALANT (WINDSCREEN) <i>11</i>	1.0	35.00	35.00
18	SubTotal (S)			85.00
19	PANEL BEAT & REPAIR REAR DAMAGE	1.0	400	1,000.00
20	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0	400	900.00
21	TO PROVIDE UNDER TURF COAT	1.0	11 X	150.00
22	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0	20	50.00
23	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0	11 X	150.00
24	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0	Repairs X	80.00
25	TO TRANSFER REAR BOOT FITTING	1.0	11 X	120.00
26	SubTotal (LABOUR)			2,450.00

P-15805X
252
1188-41
820
2022-11



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921
Tel: +65 67412845 Fax No: +65 67412170
Email: zero_gravity@singnet.com.sg
Reg.No.: 5288887X

QUOTATION

No : QT-000310

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD
#09-01
SINGAPORE 068897

TEL : 63953836

FAX :

Your Ref. : SNE5651X
Vehicle No. : SLK9938K
Make & Model : TOYOTA HARRIER
Chasis No. : ZSU600081943
Engine No. : 3ZRB812314
Accident Date : 03-10-2022
Policy No. : 5086814981-05
Date : 04-10-2022
Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE DOLLAR SIX THOUSAND THREE HUNDRED FIFTY SEVEN AND CENTS SEVENTY NINE ONLY

E. & O.E

Total	S\$	6,357.79
Discount	S\$	0.00
Net Total	S\$	6,357.79

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.