

CS/ASM 22.009888 / Tng 3

WE-31 DEC 2028

Date:

Veh No: FRD 4452 H Yr Regn: 2007, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Spark T135 c.c 135

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading T/Radio: Insured / Std / NI / NA.

Eng/No: _____

C/No: 59P300832.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Ni / S/Rim / STD A/Rim or

Tyre Size: F: 70/90R17

R: 80/40 R12.

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal.	mm	L/Bal.	mm
--------	----	--------	----

D.O.A. D.O.I. 6/18/77

Survey held at Swat Lee

Des. of Damages : Front / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐: Prell. Report

Days Of Repair:

Final: Final Report

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

1	Interview (\$
---	---------------

☐ Tech. Invs (9)

1. Wesley (S)

Survey Fee:

Transportation:

$$S \div RS. \quad SI$$

Photos

Others

795

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before spray painting
 - To display damaged part(s) during survey
 - Parts prices are subject to confirmation
 - Third party survey is on a "With-out-repairer" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be surveyed and is subject to final approval from insurance company

REG. NO. 201918537M
EMAIL : enquiry@erzatileemotor.com
Office : 69661751

Acknowledged by Repairer
Signature:

ESTIMATE COST OF REPAIR

Date: 5-Oct-22

Estimate no.

1169

Plate No. FBD4452H

Model. YAMAHA SPARK 135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 450.00	?	
2	FORK T-UNDER BRACKET	\$ 280.00	?	
3	STEERING CONE	\$ 150.00	?	
4	FRONT TYRES SHAFT	\$ 100.00	K	
5	FRONT SPORT RIM	\$ 250.00	x	
6	FRONT FENDER	\$ 180.00	cut	
7	HANDLE BAR	\$ 280.00	?	
8	HANDLE BRACKET	\$ 180.00	?	
9	MIRROR SET	\$ 120.00	cut	
10	CLUTH LEVEL	\$ 80.00	cut	
11	HANDLE BALANCER	\$ 100.00	cut	
12	HEAD LAMP	\$ 180.00	?	
13	HEAD LAMP STAY	\$ 150.00	?	
14	INNER PANEL	\$ 200.00	cut	
15	BASKET	\$ 120.00	bt	
16	FRONT FAIRING COVER LEFT	\$ 200.00	cut	
17	RADIATOR COOLANT	\$ 285.00	disassemble	
18	FRONT FOOTREST RUBBER	\$ 100.00	cut	
19	FRONT FOOTREST BAR	\$ 220.00	bt	
20	FRONT SPROKET COVER	\$ 120.00	cut	
21	REAR FOOTREST LEFT	\$ 120.00	bt	
22	REAR FOOTREST BRACKET LEFT	\$ 180.00	cut	
23	GEAR PEDAL	\$ 150.00	bt	
24	FRONT FAIRING INNER COVER LEFT	\$ 120.00	dis	
25	REAR BOX	\$ 450.00	cut	
26	DAY LIGHT	\$ 250.00	?	
27	FRONT PANEL COVER	\$ 180.00	cut	
28	REAR FAIRING COVER	\$ 220.00	cut	
29	LABOUR	\$ 500.00	300	

Tanfiah 97415749 / 62563561

Wp 6/10/22 @ 240pm

L/S Resurvey after repair

Tanfiah@lkkauto.com

3 days

- To check consistency of accident

- To check part prices

Less 10% \$ 591.50

\$ 5,915.00

Sub Total : \$ 5,323.50

GST 7% \$ 372.65

Total: \$ 5,696.15

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.