

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 06.10.2022

MODEL: Hyundai Ioniq

VEHICLE NO.: SHA6445K

INSURANCE: INCOME (LKS)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Radiator Grille	1		\$ 1,409.10
	Front Bumper Cover	1		\$ 481.10
	Front Bumper Upper Moulding	1		\$ 368.50
	Front Bumper Lower Grille	1		\$ 318.80
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	DayLight Grille LH	1		\$ 93.45
	HeadLamp LH	1		\$ 2,110.30
	SUB TOTAL		4484.45	\$ 4,803.25
	LESS 20%			\$ 960.65
	DISCOUNTED TOTAL		3587.56	\$ 3,842.60
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge		630	\$ 300.00
	Check Lightings			\$ 40.00
	TOTAL LABOUR		427.56	\$ 770.00
	ESTIMATE TOTAL		4593350	\$ 4,612.60
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanjin 9249849
6/16/22 @ 430pm
02 days
45.00 per hour
Tanjin C. Chantawon

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: