

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0218/2022
DATE : 06-OCT-2022

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : DOWNTOWN TRAVEL SERVICES PTE LTD
ADDRESS : 911 BUKIT TIMAH ROAD

TELEPHONE NO : S(589622)

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 79900000060/120000227
VEHICLE NO : SMQ7869X
MODEL CODE : GK7CKBL
MODEL/YEAR : IMPREZA 4D 2.0I-S EYESIGHT AWD CVT
ENGINE NO : FB20CE38671
CHASSIS NO : JF1GK7KL5KG011863
MILEAGE : 1 KM
DATE IN : 06/10/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 06/10/2022

Print Date : 06/10/2022
Print Time : 11:05:58

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMQ7869X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST CHINA TAIPING (SLM885C)		
2	ZZ/001	DOA:04/10/2022 TIME:1725HRS LOCATION:ZION ROAD		
3	ZZ/002	REPLACE FRONT HOOD,FRT BUMPER,FRT LH FENDER, SUPPORT PANEL	2480.00	
4	ZZ/003	RESPRAY FRONT HOOD,FRT BUMPER,FRT LH FENDER, SUPPORT PANEL	2160.00	
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	
6	ZZ/005	TO CONDUCT (FRONT) LIGHTING TEST	50.00	
7	ZZ/006	FAULT DIAGNOSTIC (RESET)	280.00	
8	ZZ/007	SUNDRIES	100.00	
		TOTAL LABOUR CHARGES	5170.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ7869X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	RAD PNL COMPL RPR	53029FL0819P	387.20			
2	FENDER F LH	57120FL0309P	222.00			
3	HOOD COMPL F	ORDER TCS 57229FL0109P	1102.60			
4	COVER FENDER UPR LH	57256FL010	18.50			
5	BUMPER FACE F STDFHI	57704FL000	447.70			
6	ENR ABSORB PL UPR	57705FL001	67.70			
7	ENR ABSORB FOAM STD	57705FL020	61.80			
8	ENR ABSORB LWR F STD	57705FL070	39.00			
9	BRKT CORNER F FHILH	57707FL010	37.00			
10	BRKT SD F RH	57707FL020	22.20			
11	BRKT SD F LH	57707FL030	22.20			
12	BRKT CTR LWR F FHI	57707FL060	37.00			
13	BEAM COMPL F EU	57711FL0109P	355.60			
14	PLATE UPR F	57722FL100	29.60			
15	COVER FOG F STD LH	57731FL050	66.60			
16	COVER INT F STD FHI	57731FL100	55.50			
17	COVER HOOK F STD	57731FL120	11.10			
18	COVER UPR F FHI	57731FL150	23.30			
19	SEALING BUMPER F FHI	57735FL000	22.20			
20	MUD GUARD ASSY F LH	59110FL030	111.00			
21	LAMP ASSY HEAD	84002FL110	2520.00			
22	GRILLE F BASE FHI	91122FL000	111.00			
23	MOLDING WG PLT FHI	91123FL020	111.00			
24	MOLDING WG PLT FHI	91123FL030	111.00			
25	MOLDING RNG PAINTFHI	91123FL050	133.20			

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMQ7869X

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
SUB TOTAL		6126.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		1225.20	0.00	0.00	0.00
GRAND TOTAL		4900.80	0.00	0.00	0.00
OVERALL TOTAL		4900.80			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMQ7869X

TOTAL LABOUR CHARGES	5170.00
TOTAL SPARE PARTS CHARGES	4900.80
	<hr/>
GRAND TOTAL	10070.80 *
	<hr/>

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.