

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009897/TVY3Q2**Date:** 24/05/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00113662200		
Claimant Vehicle No :	XE8868A	Insured Vehicle No :	SJF1117R		
Date of Loss:	05/10/2022	Nature of Claim:	TP	Claim No:	SNM22D207171/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE8868A	Engine No:	6WG1424859
Make & Model:	ISUZU CYZ52R, 15.7 D (M)	Chassis No:	JALCYZ52RF7000081
Reg. Date:	21/01/2016 (Man. Year: 2015)	Odometer:	186947 km
Colour:	Orange		
Engine Capacity:	15681 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80R 22.5	Rear Tyre Size:	315/80R 22.5 (D)
Front Left Side:	AVSTYRE 8 mm	Rear Left Side:	AVSTYRE 8/8 mm
Front Right Side:	AVSTYRE 8 mm	Rear Right Side:	AVSTYRE 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,217.78	2,197.35	3,020.43	57.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	920.00	600.00	320.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,137.78	2,797.35	3,340.43	54.42
+ GST 8.00/8.00% (S\$)	491.02	223.79	267.23	54.42
Nett Amount (S\$)	6,628.80	3,021.14	3,607.66	54.42

INSPECTION

Date of Assignment:	07/10/2022	
Date Inspected:	18/10/2022 Inspected At:	Kan Fook Sing Motor Workshop (Defu) Blk 8 Defu South Street 1, Defu Industrial City #04-29 Singapore 533758
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,059.06 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 May 2023)	
Parts:	N/A	ISUZU CYZ52R 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE8868A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER SIDE (LH)	Bent	545.00 FL	*545.00 FL	
2	1		*FRONT BUMPER HEAD LAMP (LH)	Not Necessary	1,128.80 FL	*- FL	
3	1		*FRONT BUMPER SIDE LAMP (LH)	Not Necessary	285.80 FL	*- FL	
4	1		*FRONT BUMPER BRACKET (LH)	*Check	325.00 FL	*- FL	
5	1		*FRONT BUMPER SIDE COVER (LH)	Distorted	208.00 FL	*208.00 FL	
6	1		*FRONT BUMPER HEAD LAMP RIM (LH)	Cut	368.00 FL	*368.00 FL	
7	1		*FRONT STEP GARNISH (LH)	Cracked	867.00 FL	*867.00 FL	
8	1		*FRONT STEP PLATE (3 PCS)	Dented (1 PCS ONLY)	975.00 FL	*325.00 FL	
9	1		*FRONT WHEEL ARCH GARNISH (LH)	*Check	789.80 FL	*- FL	
Sub Total (\$)						5,492.40	2,313.00
- List Item Discount on L Items 5.00/5.00% (\$)						274.62	115.65
Total Parts (\$)						5,217.78	2,197.35

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS ,WELD ,CUT PANEL BEATING & RENEW PARTS	New	520.00	300.00
2	SPRAY PAINTING	New	400.00	300.00
			Gross Labour Cost (S\$)	920.00
				600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >