



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD #16-00 SPRINGLEAF TOWER
SINGAPORE 079909

DATE : 07-10-2022

VEHICLE NO. : XE8868A
ACCIDENT DATE : 05-10-2022 08:15
THIRD PARTY REF. : SJF1117R

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE XE8868A ISUZU CYZ52R

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BUMPER SIDE (LH)	545.00 <i>bt</i>
2	1	FRONT BUMPER HEAD LAMP (LH)	1128.80 x
3	1	FRONT BUMPER SIDE LAMP (LH)	285.80 x
4	1	FRONT BUMPER BRACKET (LH)	325.00 ?
5	1	FRONT BUMPER SIDE COVER (LH)	208.00 <i>dis</i>
6	1	FRONT BUMPER HEAD-LAMP RIM (LH)	368.00 <i>cut</i>
7	1	FRONT STEP GARNISH (LH)	867.00 <i>cut</i>
8	1	FRONT STEP PLATE @\$325.00	975.00 <i>lower step plate dd</i>
9	1	FRONT WHEEL ARCH GARNISH (LH)	789.80 ?
			<hr/>
			5,492.40
			LESS 5 %
			<hr/>
			274.62
			<hr/>
			TOTAL (A)
			<hr/>
			5,217.78

LABOUR CHARGES

1	1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD. CUT, PANEL BE-ATIGN & RENEW PARTS	520.00 <i>300</i>
2	1	SPRAY PAINTING	400.00 <i>300</i>
			<hr/>
			TOTAL (D)
			<hr/>
			920.00
			<hr/>
			ESTIMATE TOTAL
			<hr/>
			6,137.78

Tanfiam 97495749 / 62565561
 WP' 18/10/22 @ 945an
 tanfiam@lkhants.com.
 3 days
 * Resurvey new parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature: